

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: DIRTY [x]
Owner :		Mileage :	176779 KM
File nr. :	1453168	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1ELJ700 / VF1FLB1AEDV439470 /		yr of constructionr :	/
E-File nr. :		First registration :	14/01/2013
VFS-nr. :		Color :	WHITE
Make + Model :	RENAULT / TRAFIC	Fuel type :	DIESEL
Object nr. :	48582	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	SPIE BELGIUM NV/SA	Co2:	180g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	TRUCK, LORRY	Seats (minivan) :	0
Vehicle type :	TRAFIC 29 B/F L1H1 Gr.Conf.FAP(EU5) 115PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	
Variant car:	BESTELWAGEN	Engine size:	1995
Gear box :	Manueel	Number of places:	3
Number of gears:	6	Number of doors:	5
HP:	114	kW:	84
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :			Oil level :	OK [x]
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	UNIROYAL	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :		
Wheel RL :	[x]	UNIROYAL	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :		
Wheel FR :	[x]	UNIROYAL	Tyre :	[x]	OK	[x]	4-6/	Rim :	/	Hubcap :	[x] MISSING/INCOMPLETE
Wheel RR :	[x]	UNIROYAL	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :		
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :		

[x]	Width	Height	Type	Rim	Index
Front tyre	215	65	R	16	
Rear tyre	215	65	R	16	

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/RIGHT/RIGHT		SCRATCH WITH PAINT DAMAGE			
	Number	Code	Description	Unit price	Depr.	Total
4	I 1	i-vab-kunst-01	PLASTICS REPAIR	110.64 EUR		110.64 EUR
[x]	REAR MUDGUARD/LEFT/FRONT		SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR		231.15 EUR		50 %	231.15 EUR
[x]	REAR MUDGUARD/RIGHT/FRONT		SCRATCH WITH PAINT DAMAGE		+DEUK	
			Repair paint - LI	New paint - E	Depr.	Total
5	0 LU =0.00 EUR		231.15 EUR		50 %	231.15 EUR
[x]	REAR DOOR/LEFT/REAR		SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR		238.76 EUR		50 %	238.76 EUR
[x]	FRONT DOOR/RIGHT/REAR		SCRATCH WITH PAINT DAMAGE		+DEUK	
			Repair paint - LI	New paint - E	Depr.	Total
6	0 LU =0.00 EUR		238.76 EUR		50 %	238.76 EUR

Interior

[x]	SEAT FL		CUT / TORN			
	Number	Code	Description	Unit price	Depr.	Total
7	I 1	i-vab-intvnl-01	VINYL REPAIR	82.20 EUR		82.20 EUR
	Number	Code	Description	Unit price	Depr.	Total
7	I 1	i-vab-intvnl-02	SUPPL VINYL REPAIR	18.00 EUR		18.00 EUR

Others

CLEANLINESS INTERIOR

	Number	Code	Description	Unit price	Depr.	Total
1	I 6	bestelwagen-cabine-a-vab-rein-05	CLEANING INTERIOR	11.47 EUR		68.82 EUR
			Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR				50 %	

HUB CAP FR

Pieces

Number	Code	Description	Unit price	Depr.	Total
2	1	WHEEL CAP	22.50 EUR	50 %	22.50 EUR

1	2	3	4	5	6	7	8	9	10
68.82	22.50	469.91	110.64	231.15	238.76	100.20	0	0	0
68.82	11.25	234.96	110.64	115.58	119.38	100.20	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
279.66	962.32	0	1241.98
HOG: 0	BG: 3		NA Deprec. 760.82
			0.00%
			TOTAL 760.82

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 02/11/2017 Hour : Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	