

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	67474
File nr. :	1453316	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1CSE722 / VF37A9HF0CJ540425 /		yr of constructionr :	2012 / 00
E-File nr. :		First registration :	15/02/2012
VFS-nr. :		Color :	GREY
Make + Model :	PEUGEOT / PARTNER	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	SBS BELGIUM NV	Co2:	140g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	TRUCK, LORRY	Seats (minivan) :	0
Vehicle type :	PARTNER B/F L1H1 Conf.120 FAP(EU5)90PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BESTELWAGEN	Engine size:	1560
Gear box :	Manueel	Number of places:	2
Number of gears:	5	Number of doors:	5
HP:	90	kW:	66
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK
Cert. of reg. / Part 1:		Cert. of conformity :	OK
Cert. of reg. copy / Part 2:	OK	Insurance certificate :	[x]
Warning vest :	[x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	OK
Fuel card :		Car radio :	OK
Mobile phone kit :		Extinguisher :	OK
First aid kit :	OK	Warning triangle :	OK
Jack, wheelspanner :	OK	Oil level :	OK
		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	MICHELIN	Tyre :	OK	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RL :	MICHELIN	Tyre :	OK	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel FR :	MICHELIN	Tyre :	OK	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	MICHELIN	Tyre :	OK	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RES:	[x]	Tyre :	OK	[x]	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	195	65	R	15	T
Rear tyre	195	65	R	15	T

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER/SIDE/LEFTCENTER	SCRATCH WITH PAINT DAMAGE	
[x]	REAR MUDGUARD/LEFT/FRONT	DENT	
[x]	FRONT DOOR/LEFT/REAR	DENT	
	WINDSCREEN/CENTER/LEFT	CHIPS	
[x]	FRONT DOOR/RIGHT/REAR	DENT	
[x]	BONNET/CENTER/LEFT	OTHER DAMAGES	ISOLATIE
[x]	FRONT BUMPER/LEFT	SCRATCH WITH PAINT DAMAGE	
[x]	FRONT BUMPER/RIGHT	SCRATCH WITH PAINT DAMAGE	

STATUS: NOT ACCEPTABLE

Interior

[x]	BOOT IN L	MISSING/INCOMPLETE		
		Repair paint - LI	New paint - E	Depr.
1	0 LU =0.00 EUR	0 EUR		50 %

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	AFDEKKING	25.00 EUR	50 %	25.00 EUR

1	2	3	4	5	6	7	8	9	10
25.00	0	0	0	0	0	0	0	0	0
12.50	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	25.00	0	25.00
HOG: 0	BG: 3		NA Deprec. 12.50
			0.00%
			TOTAL 12.50

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 30/10/2017 Hour : 13:39 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	