

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	179973 KM
File nr. :	1456288	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1HNU881 / VSSZZZ7NZFV505325 /		yr of constructionr :	/
E-File nr. :		First registration :	01/09/2014
VFS-nr. :		Color :	BROWN
Make + Model :	SEAT / ALHAMBRA	Fuel type :	DIESEL
Object nr. :	12308	Fuel :	
Classification :	I	Environment Class:	EURO 5
Customer company :	XELLA BELGIE NV	Co2:	148g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	7 [x]
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	MONOVOLUME	Engine size:	1968
Gear box :	Manueel	Number of places:	7
Number of gears:	6	Number of doors:	5
HP:	140	kW:	103
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	OK	[x]
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :	OK	[x]	Oil level :	OK
		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	CONTINENTAL	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RL :	[x]	CONTINENTAL	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel FR :	[x]	CONTINENTAL	Tyre :	[x]	OK	[x]	2-4/	Rim :	/
Wheel RR :	[x]	CONTINENTAL	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RES:	[x]		Tyre :	OK	/		Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	215	60	R	16	H
Rear tyre	215	60	R	16	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] REAR BUMPER/CENTER/RIGHT SCRATCH WITH PAINT DAMAGE
- [x] FRONT MUDGUARD/LEFT/CENTER SCRATCH WITH PAINT DAMAGE
- [x] BONNET/CENTER/RIGHT OTHER DAMAGES POLIEREN
- [x] FRONT BUMPER/CENTER/RIGHT SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	FRONT DOOR/RIGHT/REAR	DENT		
	Repair paint - LI	New paint - E	Depr.	Total
	2 0 LU =0.00 EUR	382.02 EUR	50 %	382.02 EUR
[x]	LIGHTS/RIGHT/FRONT	HOLE/CRACK/TORN		
	Repair paint - LI	New paint - E	Depr.	Total
	1 5 LU =24.00 EUR	0 EUR	50 %	24.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	FOG LAMP	108.00 EUR	50 %	108.00 EUR

1	2	3	4	5	6	7	8	9	10
132.00	382.02	0	0	0	0	0	0	0	0
66.00	191.01	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	514.02	0	514.02
HOG: 0	BG: 2		NA Deprec. 257.01
			0.00%
			TOTAL 257.01

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 06/11/2017 Hour : 16:09 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	