

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	109649 KM
File nr. :	1456395	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1BLO056 / YV1MS84F1C2566422 /		yr of constructionr :	/
E-File nr. :		First registration :	28/06/2011
VFS-nr. :		Color :	GREY
Make + Model :	VOLVO / S40	Fuel type :	DIESEL
Object nr. :	52167	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	Desk Solutions nv	Co2:	99g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	S40 BER DRIVe Start/Stop 99g 115PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BERLINE	Engine size:	1560
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	4
HP:	114	kW:	84
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK
Cert. of reg. / Part 1:		Cert. of conformity :	OK
Cert. of reg. copy / Part 2:	OK	Insurance certificate :	
Warning vest :	OK [x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	OK [x]
Fuel card :		Car radio :	OK
Mobile phone kit :		Extinguisher :	
First aid kit :	OK [x]	Warning triangle :	OK
Jack, wheelspanner :	OK	Oil level :	OK
		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	CONTINENTAL	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	
Wheel RL :	[x]	CONTINENTAL	Tyre :	OK		4-6/	Rim :	/	Hubcap :	
Wheel FR :	[x]	CONTINENTAL	Tyre :	[x]	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel RR :	[x]	CONTINENTAL	Tyre :	OK		4-6/	Rim :	/	Hubcap :	
Wheel RES:	[x]	CONTINENTAL	Tyre :	OK		>6/	Rim :	/	Hubcap :	

	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	V
Rear tyre	205	55	R	16	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	WINDSCREEN/CENTER/LEFT	CHIPS
[x]	FRONT MUDGUARD/LEFT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	BONNET/CENTER/LEFT/FRONT	CHIPS
[x]	FRONT BUMPER/CENTER/LEFT	CHIPS

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	ROOF/FRONT/CENTER/RIGHT	OTHER DAMAGES	CHEMISCHE INWERKING	
		Repair paint - LI	New paint - E	
			Depr.	
			Total	
1	0 LU =0.00 EUR	481.50 EUR	50 %	481.50 EUR

1	2	3	4	5	6	7	8	9	10
481.50	0	0	0	0	0	0	0	0	0
240.75	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	481.50	0	481.50
HOG: 0	BG: 0		NA Deprec. 240.75
			0.00%
			TOTAL 240.75

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 08/11/2017 Hour : 16:33 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	