

D90WLY

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: DIRTY [x]
Owner :		Mileage :	183583 KM
File nr. :	1455938	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DFS703 / WVWZZZ3CZCE081165 /		yr of constructionr :	/
E-File nr. :		First registration :	07/05/2012
VFS-nr. :		Color :	GREY
Make + Model :	VOLKSWAGEN / PASSAT BREAK	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :	F	Environment Class:	EURO 5
Customer company :	DISTRI-LOG NV	Co2:	116g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	1 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	105	kW:	77
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK
Cert. of reg. / Part 1:		Cert. of conformity :	OK
Cert. of reg. copy / Part 2:	OK	Insurance certificate :	
Warning vest :	OK	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	OK
Mobile phone kit :		Extinguisher :	OK
First aid kit :	OK	Warning triangle :	OK
Jack, wheelspanner :	OK	Oil level :	OK
		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :		Hubcap :	
Wheel RL :	PIRELLI	Tyre :	OK	[x]	4-6/	Rim :		Hubcap :	
Wheel FR :	MICHELIN	Tyre :	[x]	OK	[x]	4-6/	Rim :		Hubcap :
Wheel RR :	PIRELLI	Tyre :	OK	[x]	4-6/	Rim :		Hubcap :	
Wheel RES:	[x]	Tyre :	OK		2-4/	Rim :		Hubcap :	

	Width	Height	Type	Rim	Index
Front tyre	215	55	R	16	H
Rear tyre	215	55	R	16	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :		Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :		Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :		Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :		Hubcap :	

	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR MUDGUARD/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE
[x]	REAR DOOR/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE
[x]	BONNET/CENTER/RIGHT/FRONT	CHIPS

Interior

SEAT FL	OTHER DAMAGES
---------	---------------

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/LEFT/LEFT	SCRATCH WITH PAINT DAMAGE	DEUK IN SIERLIJST CHROOM		
		Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE	+DEUK		
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR
[x]	BONNET/CENTER/LEFT	DENT			
Number	Code	Description	Unit price	Depr.	Total
1	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
3	1	CHROOMLIJST	20.00 EUR	50 %	20.00 EUR

1	2	3	4	5	6	7	8	9	10
63.00	318.35	231.80	0	0	0	0	0	0	0
63.00	159.18	115.90	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
63.00	550.15	0	613.15
HOG: 0	BG: 0		NA Deprec. 338.08
			0.00%
			TOTAL 338.08

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : SCHADE 1 AANGEGEVEN BIJ BEDRIJF Date : 02/11/2017 Hour : Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	