

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	167988 KM
File nr. :	1454791	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FME875 / YV1MV8481E2094781 /		yr of constructionr :	/
E-File nr. :		First registration :	14/08/2013
VFS-nr. :		Color :	BLUE
Make + Model :	VOLVO / V40	Fuel type :	DIESEL
Object nr. :	68236	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	MERKATOR NV	Co2:	88g/km
Driver :		Remote controls:	2
Covering :	TISSUE-LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	V40 D2 Base 115PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1560
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	114	kW:	84
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	OK [x]
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :			Oil level :	OK [x]
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	CONTINENTAL	Tyre :	OK	/	Rim :		Hubcap :
Wheel RL :	[x]	CONTINENTAL	Tyre :	OK	/	Rim :		Hubcap :
Wheel FR :	[x]	CONTINENTAL	Tyre :	OK	/	Rim :		Hubcap :
Wheel RR :	[x]	CONTINENTAL	Tyre :	OK	/	Rim :		Hubcap :
Wheel RES:	[x]		Tyre :	OK	/	Rim :		Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	H
Rear tyre	205	55	R	16	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Interior

[x] DOOR IN FL

OTHER DAMAGES

STATUS: NOT ACCEPTABLE

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 2	specifiek-per-kwartier-a-vab-rein-03 CLEANING INTERIOR	14.58 EUR		29.16 EUR

1	2	3	4	5	6	7	8	9	10
29.16	0	0	0	0	0	0	0	0	0
29.16	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
29.16	0	0	29.16
HOG: 0	BG: 0		NA Deprec. 29.16
			0.00%
			TOTAL 29.16

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 03/11/2017 Hour : Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	