

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	104295 KM
File nr. :	1453662	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1EFI492 / JTDZS3EU903044222 /		yr of constructionr :	/
E-File nr. :		First registration :	15/11/2012
VFS-nr. :		Color :	BLACK
Make + Model :	TOYOTA / PRIUS	Fuel type :	HYBRID
Object nr. :	74517	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	Nos Energies GIE	Co2:	96g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	1 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :	GRAND PRIUS+ Hybrid Comfort 98PK Aut.	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1798
Gear box :	Automaat algemeen	Number of places:	5
Number of gears:		Number of doors:	4
HP:	99	kW:	73
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number : OK	Service manual : OK [x]
Cert. of reg. / Part 1:	Cert. of conformity : OK
Cert. of reg. copy / Part 2: OK [x]	Insurance certificate :
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher : OK [x]
First aid kit : OK [x]	Warning triangle : OK [x]
Jack, wheelspanner : OK [x]	Oil level : OK [x]
	Filled up : 0

Wheels and tyres: Summer tires

Wheel FL: [x] MICHELIN Tyre : OK [x] 2-4/ Rim : [x] BROKEN DOWN / DAMAGED / Hubcap : [x] MISSING/INCOMPLETE
Wheel RL : [x] MICHELIN Tyre : OK [x] 2-4/ Rim : / Hubcap : [x] SCRATCHED
Wheel FR : [x] MICHELIN Tyre : [x] OK [x] 2-4/ Rim : / Hubcap : [x] SCRATCHED
Wheel RR : [x] MICHELIN Tyre : OK [x] 2-4/ Rim : / Hubcap : [x] SCRATCHED
Wheel RES: [x] MICHELIN Tyre : OK [x] >6/ Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	205	60	R	16	H
Rear tyre	205	60	R	16	H

Remark :

Wheels and tyres:

Wheel FL: Tyre : OK / Rim : / Hubcap :
Wheel RL : Tyre : OK / Rim : / Hubcap :
Wheel FR : Tyre : OK / Rim : / Hubcap :
Wheel RR : Tyre : OK / Rim : / Hubcap :
Wheel RES: Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR MUDGUARD/LEFT/Front	SCRATCH WITH PAINT DAMAGE
[x]	REAR DOOR/LEFT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	ROOF/REAR/RIGHT	DENT
[x]	REAR DOOR/RIGHT/Front	SCRATCH WITH PAINT DAMAGE
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE
[x]	FRONT DOOR/RIGHT/REAR	DENT
[x]	FRONT MUDGUARD/LEFT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)

Interior

[x]	BOOT LID IN	SCRATCHED
-----	-------------	-----------

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/RIGHT	DENT			
			Repair paint - LI	New paint - E	Depr.
					Total
3	5 LU =24.00 EUR		211.80 EUR		50 %
					235.80 EUR
[x]	REAR LIGHT/RIGHT	SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E	Depr.
					Total
4	5 LU =24.00 EUR		0 EUR		50 %
					24.00 EUR
[x]	REAR MUDGUARD/RIGHT/Front	OTHER DAMAGES			SLECHT HERSTELD
			Number	Code	Description
					Unit price
					Depr.
					Total
0	0				
[x]	REAR THRESHOLD/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE			
			Number	Code	Description
					Unit price
					Depr.
					Total
1	I 1 i-vab-sp-01	SPOTREPAIR		115.56 EUR	
					115.56 EUR
[x]	FRONT BUMPER/CENTER/LEFT	DENT			
			Repair paint - LI	New paint - E	Depr.
					Total
2	5 LU =24.00 EUR		211.80 EUR		50 %
					235.80 EUR

Accessories and others

[x]	OUTSIDE MIRROR RIGHTHAND SIDE	SCRATCH WITH PAINT DAMAGE			
Number	Code	Description	Unit price	Depr.	Total
7	I 1 i-vab-kunst-01	PLASTICS REPAIR	110.64 EUR		110.64 EUR

Others

RIM FRONT LEFT					
		Repair paint - LI	New paint - E	Depr.	Total
5	5 LU =24.00 EUR			50 %	24.00 EUR
HUB CAP REAR L					
		Repair paint - LI	New paint - E	Depr.	Total
6	0 LU =0.00 EUR			50 %	
HUB CAP REAR RIGHT					
		Repair paint - LI	New paint - E	Depr.	Total
6	0 LU =0.00 EUR			50 %	
HUB CAP FR					
		Repair paint - LI	New paint - E	Depr.	Total
6	0 LU =0.00 EUR			50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
4	1	REAR LIGHT	90.00 EUR	50 %	90.00 EUR
Number	Code	Description	Unit price	Depr.	Total
6	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR
Number	Code	Description	Unit price	Depr.	Total
6	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR
Number	Code	Description	Unit price	Depr.	Total
5	1	ALLOY WHEEL	211.20 EUR	50 %	211.20 EUR
Number	Code	Description	Unit price	Depr.	Total
5	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR
Number	Code	Description	Unit price	Depr.	Total
6	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR

1	2	3	4	5	6	7	8	9	10
115.56	235.80	235.80	114.00	265.20	90.00	110.64	0	0	0
115.56	117.90	117.90	57.00	132.60	45.00	110.64	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
226.20	940.80	0	1167.00
HOG: 0	BG: 0		NA Deprec. 696.60
			0.00%
			TOTAL 696.60

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 06/11/2017 Hour : 09:33 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	