

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	77304 KM
File nr. :	1456899	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DQE194 / WV2ZZZ2KZDX016260 /		yr of constructionr :	/
E-File nr. :		First registration :	19/07/2012
VFS-nr. :		Color :	GREY
Make + Model :	VOLKSWAGEN / CADDY	Fuel type :	DIESEL
Object nr. :	ONBEKEND	Fuel :	
Classification :	DELIVERY VAN A	Environment Class:	EURO 5
Customer company :	ONBEKEND	Co2:	g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	TRUCK, LORRY	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:		Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	5
HP:	102	kW:	75
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :		Transport licence :		
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :	[x]		Oil level :	OK
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	CONTINENTAL	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RL :	[x]	CONTINENTAL	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel FR :	[x]	CONTINENTAL	Tyre :	[x]	OK	[x]	2-4/	Rim :	/
Wheel RR :	[x]	CONTINENTAL	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RES:	[x]		Tyre :	OK	/		Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	H
Rear tyre	205	55	R	16	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]					
		Repair paint - LI	New paint - E	Depr.	Total
	REAR WINDOW STYLE/CENTER/LEFT/UP		HOLE/CRACK/TORN		
3	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR
	REAR MUDGUARD/RIGHT/FRONT		DENT		
4	0 LU =0.00 EUR	231.15 EUR		50 %	231.15 EUR
	REAR DOOR/RIGHT/REAR		SCRATCH WITH PAINT DAMAGE		
4	0 LU =0.00 EUR	238.76 EUR		50 %	238.76 EUR
	REAR THRESHOLD/RIGHT/REAR		SCRATCH WITH PAINT DAMAGE		
4	0 LU =0.00 EUR	232.88 EUR		50 %	232.88 EUR
	BONNET/CENTER/LEFT/FRONT		OTHER DAMAGES	ISOLATIE	
1	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

Accessories and others

[x]					
		Repair paint - LI	New paint - E	Depr.	Total
	OUTSIDE MIRROR LEFTHAND SIDE		MISSING/INCOMPLETE		
2	0 LU =0.00 EUR	0 EUR		50 %	

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 3	specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR	43.74 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	ISOLATIE	50.00 EUR	50 %	50.00 EUR
2	1	KADER SPIGEL	40.00 EUR	50 %	40.00 EUR
3	1	STOPLICHT	25.00 EUR	50 %	25.00 EUR

1	2	3	4	5	6	7	8	9	10
117.74	40.00	49.00	702.79	0	0	0	0	0	0
80.74	20.00	24.50	351.40	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
43.74	865.79	0	909.53
HOG: 0	BG: 3		NA Deprec. 476.64
			0.00%
			TOTAL 476.64

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 07/11/2017 Hour : 09:24 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	