

D85QR1

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: CLEAN [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	81394 KM
<b>File nr. :</b>	1455276	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1FTW142 / VF15RJL0H49648192 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	23/10/2013
<b>VFS-nr. :</b>		<b>Color :</b>	RED
<b>Make + Model :</b>	RENAULT / CLIO	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>	69072	<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	EURO 5
<b>Customer company :</b>	PROXIMEDIA S.A.	<b>Co2:</b>	83g/km
<b>Driver :</b>		<b>Remote controls:</b>	2
<b>Covering :</b>	TISSUE	<b>Number keys :</b>	2 [x]
<b>Vehicle kind :</b>	VEHICLE	<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>	CLIO IV BER e-Business St&St 90PK	<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>	No	<b>Metallic paint:</b>	Yes
<b>Variant car:</b>		<b>Engine size:</b>	1461
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	5
<b>Number of gears:</b>	6	<b>Number of doors:</b>	5
<b>HP:</b>	90	<b>kW:</b>	66
<b>Fisc HP</b>		<b>Imported vehicle:</b>	
<b>Animals transported:</b>	No	<b>Smoked in vehicle:</b>	No
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	No
		<b>Use:</b>	Unknown
<b>General condition:</b>			

Original registr. number :	OK	Service manual :	
Cert. of reg. / Part 1:	OK [x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :	
Warning vest :	OK [x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	OK [x]
Fuel card :		Car radio :	OK [x]
Mobile phone kit :		Extinguisher :	OK [x]
First aid kit :	OK [x]	Warning triangle :	OK [x]
Jack, wheelspanner :	OK [x]	Oil level :	OK [x]
		Filled up :	0

## Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	2-4/	Rim :	/	Hubcap :	[x]	SCRATCHED
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel RES:	[x]	MICHELIN	Tyre :	OK		/	Rim :	/	Hubcap :			

  

[x]	Width	Height	Type	Rim	Index
Front tyre	185	65	R	15	H
Rear tyre	185	65	R	15	H

Remark :

## Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :	

  

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

- [x] FRONT BUMPER/LEFT/SIDE SCRATCH WITH PAINT DAMAGE
- [x] BONNET/CENTER/LEFT/FRONT CHIPS

### Interior

- [x] DOOR IN FL OTHER DAMAGES

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	REAR MUDGUARD/RIGHT/FRONT	SCRATCH WITH PAINT DAMAGE			
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>
<b>1</b>	<b>0 LU =0.00 EUR</b>	<b>246.56 EUR</b>			<b>50 %</b>
					<b>Total</b>
					<b>246.56 EUR</b>

[x]	REAR DOOR/LEFT/REAR	OTHER DAMAGES			SLECHTE HERSTELLING/KLEUR
			<b>Number</b>	<b>Code</b>	<b>Description</b>
<b>0</b>	<b>0</b>				<b>Unit price</b>
					<b>Depr.</b>
					<b>Total</b>

[x]	REAR DOOR/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE			
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>
<b>1</b>	<b>0 LU =0.00 EUR</b>	<b>254.68 EUR</b>			<b>50 %</b>
					<b>Total</b>
					<b>254.68 EUR</b>

### Others

	HUB CAP FL				
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>
<b>2</b>	<b>0 LU =0.00 EUR</b>				<b>50 %</b>

	HUB CAP REAR L				
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>
<b>2</b>	<b>0 LU =0.00 EUR</b>				<b>50 %</b>

	HUB CAP REAR RIGHT				
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>
<b>2</b>	<b>0 LU =0.00 EUR</b>				<b>50 %</b>

	HUB CAP FR				
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>
<b>2</b>	<b>0 LU =0.00 EUR</b>				<b>50 %</b>

<b>Pieces</b>
---------------

Number	Code	Description	Unit price	Depr.	Total
2	1	WHEEL CAP	24.00 EUR	50 %	24.00 EUR
<hr/>					
Number	Code	Description	Unit price	Depr.	Total
2	1	WHEEL CAP	24.00 EUR	50 %	24.00 EUR
<hr/>					
Number	Code	Description	Unit price	Depr.	Total
2	1	WHEEL CAP	24.00 EUR	50 %	24.00 EUR
<hr/>					
Number	Code	Description	Unit price	Depr.	Total
2	1	WHEEL CAP	24.00 EUR	50 %	24.00 EUR

1	2	3	4	5	6	7	8	9	10
501.24	96.00	0	0	0	0	0	0	0	0
250.62	48.00	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	597.24	0	<b>597.24</b>
HOG: 0	BG: 1		NA Deprec. 298.62
			0.00%
			<b>TOTAL 298.62</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No <b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 03/11/2017 <b>Hour :</b> 13:17 <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
Signature authorized by customer 	