

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	153830 KM
File nr. :	1457042	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1GNN781 / JTMBA31V906027454 /		yr of constructionr :	/
E-File nr. :		First registration :	25/08/2006
VFS-nr. :		Color :	GREY
Make + Model :	TOYOTA / RAV4	Fuel type :	DIESEL
Object nr. :	ONBEKEND	Fuel :	
Classification :		Environment Class:	EURO 4
Customer company :	ONBEKEND	Co2:	173g/km
Driver :		Remote controls:	1
Covering :	LEATHER	Number keys :	1 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	SUV	Engine size:	2231
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	136	kW:	100
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:	2DE SLEUTEL WORDT MEEGELEVERD MOTORSTORING/INJECTOR		

Original registr. number :		Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK [x]	Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK [x]	Insurance certificate :		
Warning vest :	OK [x]	Transport licence :		
Tax certificate :		Navigation CD/SD/DVD	OK	[x]
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK [x]	Warning triangle :	OK	[x]
Jack, wheelspanner :	OK [x]	Oil level :	OK	[x]
		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	
Wheel RES:	[x]	MICHELIN	Tyre :	OK		/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	225	65	R	17	W
Rear tyre	225	65	R	17	W

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] REAR MUDGUARD/LEFT/CENTER DENT
- [x] FRONT BUMPER/LEFT SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

	Repair paint - LI	New paint - E	Depr.	Total
[x] REAR MUDGUARD/RIGHT/REAR SCRATCH WITH PAINT DAMAGE				
2 0 LU =0.00 EUR	308.20 EUR			308.20 EUR
[x] REAR DOOR/RIGHT/REAR SCRATCH WITH PAINT DAMAGE				
2 0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR

Interior

	Repair paint - LI	New paint - E	Depr.	Total
[x] HEAD RESTS MISSING/INCOMPLETE				
1 0 LU =0.00 EUR	0 EUR		50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	HEAD REST	60.00 EUR	50 %	60.00 EUR

1	2	3	4	5	6	7	8	9	10
60.00	626.55	0	0	0	0	0	0	0	0
30.00	467.38	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	686.55	0	686.55
HOG: 0	BG: 0		NA Deprec. 497.38
			0.00%
			TOTAL 497.38

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 07/11/2017 Hour : 13:02 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	