

D7G1LU

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: CLEAN [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	93221 KM
<b>File nr. :</b>	1454732	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1FPV316 / WV2ZZZ2KZEX040344 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	18/09/2013
<b>VFS-nr. :</b>		<b>Color :</b>	WHITE
<b>Make + Model :</b>	VOLKSWAGEN / CADDY	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>	49744	<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	EURO 5
<b>Customer company :</b>	Besix SA	<b>Co2:</b>	139g/km
<b>Driver :</b>		<b>Remote controls:</b>	2
<b>Covering :</b>	TISSUE	<b>Number keys :</b>	2 [x]
<b>Vehicle kind :</b>	VEHICLE	<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>	CADDY LIFE Baseline BM 75PK	<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>	No	<b>Metallic paint:</b>	Yes
<b>Variant car:</b>	BREAK	<b>Engine size:</b>	1598
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	5
<b>Number of gears:</b>	5	<b>Number of doors:</b>	5
<b>HP:</b>	75	<b>kW:</b>	55
<b>Fisc HP</b>		<b>Imported vehicle:</b>	No
<b>Animals transported:</b>	No	<b>Smoked in vehicle:</b>	No
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	No
		<b>Use:</b>	Unknown

**General condition:**

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :		Oil level :	OK	[x]
		Filled up :	0	

## Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	2-4/	Rim :	/
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :
Wheel RES:	[x]		Tyre :	OK	/		Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	195	65	R	15	V
Rear tyre	195	65	R	15	V

Remark :

## Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	REAR BUMPER /LEFT/CORNER		SCRATCH WITH PAINT DAMAGE		
	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>
	<b>Total</b>				
2	I 1	i-vab-kunst-01	PLASTICS REPAIR	110.64 EUR	110.64 EUR
[x]	REAR DOOR/LEFT/CENTER		SCRATCH WITH PAINT DAMAGE		
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>
					<b>Total</b>
1	0 LU =0.00 EUR		238.76 EUR		50 %
					238.76 EUR

### Interior

[x]	SEAT FR		STAIN		
	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>
	<b>Total</b>				
4	I 1	i-vab-rein-07	CLEANING (PER 15')	14.58 EUR	14.58 EUR
[x]	BOOT LID IN		OTHER DAMAGES		
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>
					<b>Total</b>
3	0 LU =0.00 EUR		0 EUR		50 %
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>
					<b>Total</b>
3	5 LU =24.00 EUR		0 EUR		50 %
					24.00 EUR

### Pieces

	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
3	1	PANEEL		20.00 EUR	50 %	20.00 EUR

<b>1</b>	<b>2</b>	<b>3</b>	<b>4</b>	<b>5</b>	<b>6</b>	<b>7</b>	<b>8</b>	<b>9</b>	<b>10</b>
238.76	110.64	44.00	14.58	0	0	0	0	0	0
119.38	110.64	22.00	14.58	0	0	0	0	0	0

<b>INNOVATIVE</b>	<b>TRADITIONAL</b>	<b>GENERAL</b>	
125.22	282.76	0	<b>407.98</b>
HOG: 0	BG: 3		<b>NA Deprec. 266.60</b>
			<b>0.00%</b>
			<b>TOTAL 266.60</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No		
<b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 07/11/2017 <b>Hour :</b> <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
<b>Signature authorized by customer</b> 	