

www.vabfleetservices.be Date: 02/10/2017 1/4

CUB803

[X] EFFECTIVE [] NOT EXECUTED	[] COLLECTION	[] DELIVERY
--------------------------------	----------------	--------------

[x] = Status Modification

Vehicle type :

VAT over the margin - car:

A4 AVANT TDie 136PK

No

Cleanliness: Commissionar: **KBC REMARKETING** INT: CLEAN [x] EXT: CLEAN [x] Owner: Mileage: 189174 KM File nr. : Mileage start / arrival: 0 / 01444420 Reg number / Chassis / Ref: Mileag ref. service : 0 yr of constructionr: 1DRJ821 / WAUZZZ8K3DA102803 / E-File nr. : First registration: 01/08/2012 VFS-nr.: Color: WHITE Make + Model : Fuel type : AUDI / A4 AVANT **DIESEL** Object nr. : Fuel: Classification: **Environment Class:** EURO 5 Customer company: Co2: COMPASS GROUP NV 116g/km Driver : Remote controls: 2 LEATHER Covering: Number keys : 2[x]Vehicle kind: VEHICLE Seats (minivan): 0

Country registration:

Metallic paint:

BELGIUM

Yes

Variant car:	BREAK	Engine size:	1968						
Gear box :	Manueel	Number of places:	5						
Number of gears:	6	Number of doors:	5						
нр:	136	kW:	100						
Fisc HP		Imported vehicle:							
Animals transported:		Smoked in vehicle:	Smoked in vehicle:						
Due date vehicle inspection:		Extra set of tires:							
		Use:	Unknown						
General condition:	General condition:								



www.vabfleetservices.be Date: 02/10/2017 2/4

Original registr. number : OK Service manual : OK [x] Cert. of conformity: Cert. of reg. / Part 1: OK Insurance certificate: Cert. of reg. copy / Part 2: OK [x]Warning vest: Transport licence: Tax certificate: Navigation CD/SD/DVD Fuel card : Car radio: OK [x] Extinguisher: Mobile phone kit : OK [x] Warning triangle: OK [x] OK Oil level: OK First aid kit : [x] [x] Filled up: 0 Jack, wheelspanner :

Wheels and tyres: Summer tires

			**** 141					1		m İ		D:	i	· ·	٦
Wheel RES:	[x]	MICHELIN	Tyre:		OK		/	Rim:				/ Hubcap:			
Wheel RR:	[x]	MICHELIN	Tyre:		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED	1	/ Hubcap:			
Wheel FR:	[x]	MICHELIN	Tyre:	[x]	OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED	1	/ Hubcap:			
Wheel RL:	[x]	MICHELIN	Tyre:		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED	1	/ Hubcap:			
Wheel FL:	[x]	MICHELIN	Tyre :		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED	1	/ Hubcap:			

[x] Width	Height	Type	Rim	Index
Front tyre	205	60	R	16	V
Rear tyre	205	60	R	16	V

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

 [x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 02/10/2017 3/4

Conclusion

Bodywork \& windows

[x] REAR DOOR/RIGHT/CENTER

SCRATCH (WITHOUT PAINT DAMAGE)

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR DOOR/LEFT/CENTER SCRATCH (WITHOUT PAINT DAMAGE)

[x] FRONT DOOR/LEFT/REAR SCRATCH (WITHOUT PAINT DAMAGE)

[x] FRONT DOOR/RIGHT/REAR SCRATCH (WITHOUT PAINT DAMAGE)

[x] BONNET/CENTER/LEFT DENT

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] REAR BUMPER/CENTER/LEFT DENT

	Repair paint - LI	New paint - E	Depr.	Total
1 0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

1	2	3	4	5	6	7	8	9	10
211.80	0	0	0	0	0	0	0	0	0
105.90	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL		
0	211.80	0		211.80
HOG: 0	BG: 0		NA Deprec.	105.90
			0.00%	
			TOTAL	105.90



www.vabfleetservices.be Date: 02/10/2017 4/4

[x] = Status Modification

Pictures: No

CIRCUMS	STANCES		NORMAL CONCLUSION				
Extra Time :	0 min	Waiting time: 0 min Reason:		Towing time: 0 min Reason:			
NOT EXECUTED Reason:): No						
Remark:							
Prices in EUR	without VAT						
Authorized by customer:			Executed by VAB Fleet S	Services			
Remark authorize	d customer :						
Date :	02/10/2017	Hour: 09:09					
Company:							
Executed by VAB Services	Fleet						
E-Mail :	@						
Signature authorized	d by customer						