

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

| | | | |
|-------------------------------------|-----------------|---------------------------------|-------------------------------|
| Commissionar : | KBC REMARKETING | Cleanliness : | INT: CLEAN [x] EXT: CLEAN [x] |
| Owner : | | Mileage : | 107663 KM |
| File nr. : | 1459679 | Mileage start / arrival: | 0 / 0 |
| Reg number / Chassis / Ref : | | Mileag ref. service : | 0 |
| 1FRI715 / WAUZZZ8K2EA047455 / | | yr of constructionr : | / |
| E-File nr. : | | First registration : | 01/10/2013 |
| VFS-nr. : | | Color : | GREY |
| Make + Model : | AUDI / A4 | Fuel type : | DIESEL |
| Object nr. : | ONBEKEND | Fuel : | |
| Classification : | G | Environment Class: | EURO 5 |
| Customer company : | ONBEKEND | Co2: | 123g/km |
| Driver : | | Remote controls: | 2 |
| Covering : | PARTIAL LEATHER | Number keys : | 2 [x] |
| Vehicle kind : | | Seats (minivan) : | 0 |
| Vehicle type : | | Country registration : | BELGIUM |

| | | | |
|-------------------------------------|---------|----------------------------|---------|
| VAT over the margin - car: | | Metallic paint: | Yes |
| Variant car: | BREAK | Engine size: | 1968 |
| Gear box : | Manueel | Number of places: | 5 |
| Number of gears: | 6 | Number of doors: | 5 |
| HP: | 120 | kW: | 88 |
| Fisc HP | | Imported vehicle: | No |
| Animals transported: | No | Smoked in vehicle: | No |
| Due date vehicle inspection: | | Extra set of tires: | No |
| | | Use: | Unknown |
| General condition: | | | |

| | | | | |
|------------------------------|----|-------------------------|-----------------------|-----|
| Original registr. number : | OK | Service manual : | OK | [x] |
| Cert. of reg. / Part 1: | OK | [x] | Cert. of conformity : | OK |
| Cert. of reg. copy / Part 2: | | Insurance certificate : | | |
| Warning vest : | | Transport licence : | | |
| Tax certificate : | | Navigation CD/SD/DVD | OK | [x] |
| Fuel card : | | Car radio : | OK | [x] |
| Mobile phone kit : | | Extinguisher : | OK | [x] |
| First aid kit : | OK | [x] | Warning triangle : | OK |
| Jack, wheelspanner : | OK | [x] | Oil level : | OK |
| | | | Filled up : | 0 |

Wheels and tyres: Winter tires

| | | | | | | | | | | | | |
|------------|-----|-------------|--------|-----|-----|------|-------|-------|--------------------|--------------------|----------|----------|
| Wheel FL: | [x] | CONTINENTAL | Tyre : | OK | [x] | >6/ | Rim : | [x] | MISSING/INCOMPLETE | / | Hubcap : | |
| Wheel RL : | [x] | CONTINENTAL | Tyre : | OK | [x] | 4-6/ | Rim : | [x] | MISSING/INCOMPLETE | / | Hubcap : | |
| Wheel FR : | [x] | CONTINENTAL | Tyre : | [x] | OK | [x] | >6/ | Rim : | [x] | MISSING/INCOMPLETE | / | Hubcap : |
| Wheel RR : | [x] | CONTINENTAL | Tyre : | OK | [x] | 4-6/ | Rim : | [x] | MISSING/INCOMPLETE | / | Hubcap : | |
| Wheel RES: | [x] | CONTINENTAL | Tyre : | OK | [x] | >6/ | Rim : | | | / | Hubcap : | |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 205 | 60 | R | 16 | M+S |
| Rear tyre | 205 | 60 | R | 16 | M+S |

Remark : ORIGINELE VELGEN OVBH

Wheels and tyres:

| | | | | | | | | |
|------------|--|--------|----|---|-------|--|---|----------|
| Wheel FL: | | Tyre : | OK | / | Rim : | | / | Hubcap : |
| Wheel RL : | | Tyre : | OK | / | Rim : | | / | Hubcap : |
| Wheel FR : | | Tyre : | OK | / | Rim : | | / | Hubcap : |
| Wheel RR : | | Tyre : | OK | / | Rim : | | / | Hubcap : |
| Wheel RES: | | Tyre : | OK | / | Rim : | | / | Hubcap : |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0 | 0 | R | 0 | |
| Rear tyre | 0 | 0 | R | 0 | |

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] REAR BUMPER/CENTER/RIGHT SCRATCH (WITHOUT PAINT DAMAGE)
- [x] WINDSCREEN/CENTER/LEFT CHIPS
- [x] BONNET/CENTER/RIGHT/FRONT CHIPS

Interior

- [x] SEAT FL SCRATCHED
- [x] SEAT REAR L STAIN

STATUS: NOT ACCEPTABLE

Bodywork \& windows

- [x] FRONT BUMPER/CENTER/RIGHT SCRATCH WITH PAINT DAMAGE

| Number | Code | Description | Unit price | Depr. | Total |
|--------|----------------|-------------|------------|-------|------------|
| 2 | I1 i-vab-sp-01 | SPOTREPAIR | 115.56 EUR | | 115.56 EUR |

Interior

- [x] SEAT FR STAIN

| Number | Code | Description | Unit price | Depr. | Total |
|--------|------------------|--------------------|------------|-------|-----------|
| 1 | I1 i-vab-rein-07 | CLEANING (PER 15') | 14.58 EUR | | 14.58 EUR |

| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
|-------|--------|---|---|---|---|---|---|---|----|
| 14.58 | 115.56 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 14.58 | 115.56 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

| INNOVATIVE | TRADITIONAL | GENERAL | |
|------------|-------------|---------|---------------------|
| 130.14 | 0 | 0 | 130.14 |
| HOG: 0 | BG: 0 | | NA Deprec. 130.14 |
| | | | 0.00% |
| | | | TOTAL 130.14 |

[x] = Status Modification


Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

| | | |
|---------------------------|--|---|
| Extra Time : 0 min | Waiting time : 0 min Reason : | Towing time : 0 min Reason : |
| NOT EXECUTED : No | | |
| Reason : | | |
| Remark : | | |

Prices in EUR without VAT

| | |
|---|--------------------------------|
| Authorized by customer : Remark authorized customer : Date : 14/11/2017 Hour : 12:35 Company : Executed by VAB Fleet Services E-Mail : @ | Executed by VAB Fleet Services |
| Signature authorized by customer  | |