

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: DIRTY [x]
Owner :		Mileage :	141126 KM
File nr. :	1456159	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FPA633 / WAUZZZ8K2EA033670 /		yr of constructionr :	/
E-File nr. :		First registration :	11/09/2013
VFS-nr. :		Color :	GREY
Make + Model :	AUDI / A4 AVANT	Fuel type :	DIESEL
Object nr. :	62381	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	SECURELINK	Co2:	123g/km
Driver :		Remote controls:	2
Covering :	PARTIAL LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	A4 AVANT TDi S-line 136PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1968
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	136	kW:	100
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	OK	[x]
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :	OK	[x]	Oil level :	OK
		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :		
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :			/	Hubcap :		
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	[x]
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :			/	Hubcap :		
Wheel RES:	[x]		Tyre :	OK		/	Rim :			/	Hubcap :		

[x]	Width	Height	Type	Rim	Index
Front tyre	245	40	R	18	Y
Rear tyre	245	40	R	18	Y

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] REAR BUMPER/CENTER/RIGHT SCRATCH WITH PAINT DAMAGE
- [x] REAR MUDGUARD/RIGHT/CENTER SCRATCH (WITHOUT PAINT DAMAGE)
- [x] ROOF/CENTER/RIGHT OTHER DAMAGES TE POLIEREN

STATUS: NOT ACCEPTABLE

Bodywork \& windows

- [x] FRONT MUDGUARD/LEFT/FRONT DENT

Number	Code	Description	Unit price	Depr.	Total
2	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR

	Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR	211.80 EUR	50 %	211.80 EUR

1	2	3	4	5	6	7	8	9	10
211.80	63.00	0	0	0	0	0	0	0	0
105.90	63.00	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
63.00	211.80	0	274.80
HOG: 0	BG: 0		NA Deprec. 168.90
			0.00%
			TOTAL 168.90

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 13/11/2017 Hour : 09:05 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	