

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: CLEAN [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	93694
<b>File nr. :</b>	1458229	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1DVH452 / WAUZZZ8X5DB029486 /		<b>yr of constructionr :</b>	2012 / 00
<b>E-File nr. :</b>		<b>First registration :</b>	07/09/2012
<b>VFS-nr. :</b>		<b>Color :</b>	GREY
<b>Make + Model :</b>	AUDI / A1 SPORTBACK	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>	46543	<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	EURO 5
<b>Customer company :</b>	ALTRAN SA	<b>Co2:</b>	99g/km
<b>Driver :</b>		<b>Remote controls:</b>	1
<b>Covering :</b>	TISSUE	<b>Number keys :</b>	2 [x]
<b>Vehicle kind :</b>		<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>	A1 SB Attraction 90PK	<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>	No	<b>Metallic paint:</b>	Yes
<b>Variant car:</b>		<b>Engine size:</b>	1598
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	4
<b>Number of gears:</b>	5	<b>Number of doors:</b>	5
<b>HP:</b>	90	<b>kW:</b>	66
<b>Fisc HP</b>		<b>Imported vehicle:</b>	
<b>Animals transported:</b>		<b>Smoked in vehicle:</b>	
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	
		<b>Use:</b>	Unknown

**General condition:**

Original registr. number : OK	Service manual : OK [x]
Cert. of reg. / Part 1:	Cert. of conformity : OK
Cert. of reg. copy / Part 2: OK [x]	Insurance certificate :
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher : OK [x]
First aid kit : OK [x]	Warning triangle : OK [x]
Jack, wheelspanner : OK [x]	Oil level : OK [x]
	Filled up : 0

## Wheels and tyres: Winter tires

Wheel FL: [x] BRIDGESTONE Tyre : OK [x] 1.6-2/ Rim : [x] BROKEN DOWN / DAMAGED / Hubcap :
Wheel RL : [x] BRIDGESTONE Tyre : OK [x] 2-4/ Rim : [x] WHEEL SCRATCHED / Hubcap :
Wheel FR : [x] BRIDGESTONE Tyre : [x] OK [x] 1.6-2/ Rim : [x] WHEEL SCRATCHED / Hubcap :
Wheel RR : [x] BRIDGESTONE Tyre : OK [x] 2-4/ Rim : [x] WHEEL SCRATCHED / Hubcap :
Wheel RES: [x] Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	185	65	R	15	WINTER T
Rear tyre	185	65	R	15	WINTER T

Remark :

## Wheels and tyres:

Wheel FL: Tyre : OK / Rim : / Hubcap :
Wheel RL : Tyre : OK / Rim : / Hubcap :
Wheel FR : Tyre : OK / Rim : / Hubcap :
Wheel RR : Tyre : OK / Rim : / Hubcap :
Wheel RES: Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	REAR DOOR/LEFT/CENTER	DENT
[x]	ROOF/CENTER/RIGHT	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	REAR DOOR/RIGHT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	FRONT DOOR/LEFT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	FRONT DOOR/RIGHT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	BONNET/CENTER/RIGHT	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	REAR DOOR/LEFT/LEFT	DENT

### Interior

[x]	SEAT REAR L	STAIN
[x]	SEAT REAR RIGHT	STAIN

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	REAR MUDGUARD/RIGHT/FRONT	DENT				
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>	
3	0 LU =0.00 EUR	246.56 EUR		50 %	246.56 EUR	
[x]	BONNET/CENTER/LEFT	OTHER DAMAGES		ISOLATIE		
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>	
5	0 LU =0.00 EUR	0 EUR		50 %		
[x]	FRONT BUMPER/RIGHT	SCRATCH WITH PAINT DAMAGE		L+R		
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>	
2	0 LU =0.00 EUR	169.44 EUR		50 %	169.44 EUR	
[x]	ROOF/CENTER/LEFT	DENT		HAGELSCHADE		
	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
0	0					

**Interior**

[x]	BACK SHELF	MISSING/INCOMPLETE			
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
1	0 LU =0.00 EUR	0 EUR		50 %	

**Others**

RIM FRONT LEFT

		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
4	0 LU =0.00 EUR			50 %	

RIM REAR LEFT

Number	Code	Description	Unit price	Depr.	Total
4	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

**Pieces**

Number	Code	Description	Unit price	Depr.	Total
1	1	CORD BACK SHELF	21.60 EUR	50 %	21.60 EUR
4	1	ALLOY WHEEL	168.96 EUR	50 %	168.96 EUR
5	1	ISOLATIE	45.00 EUR	50 %	45.00 EUR

1	2	3	4	5	6	7	8	9	10
21.60	169.44	246.56	263.96	45.00	0	0	0	0	0
10.80	84.72	123.28	179.48	22.50	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
95.00	651.56	0	<b>746.56</b>
HOG: 0	BG: 1		NA Deprec. 420.78
			0.00%
			<b>TOTAL 420.78</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No		
<b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 15/11/2017 <b>Hour :</b> 12:52 <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
Signature authorized by customer 	