

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

| | | | |
|-------------------------------------|---------------------------|---------------------------------|-------------------------------|
| Commissionar : | KBC REMARKETING | Cleanliness : | INT: CLEAN [x] EXT: CLEAN [x] |
| Owner : | | Mileage : | 220972 KM |
| File nr. : | 1458159 | Mileage start / arrival: | 0 / 0 |
| Reg number / Chassis / Ref : | | Mileag ref. service : | 0 |
| 1AHI537 / WAUZZZ8K2BA034927 / | | yr of constructionr : | / |
| E-File nr. : | | First registration : | 10/01/2011 |
| VFS-nr. : | | Color : | |
| Make + Model : | AUDI / A4 ALLROAD QUATTRO | Fuel type : | DIESEL |
| Object nr. : | ONBEKEND | Fuel : | |
| Classification : | G | Environment Class: | EURO 5 |
| Customer company : | ONBEKEND | Co2: | 164g/km |
| Driver : | | Remote controls: | 2 |
| Covering : | LEATHER | Number keys : | 2 [x] |
| Vehicle kind : | VEHICLE | Seats (minivan) : | 0 |
| Vehicle type : | | Country registration : | BELGIUM |

| | | | |
|-------------------------------------|---------|----------------------------|---------|
| VAT over the margin - car: | | Metallic paint: | Yes |
| Variant car: | BREAK | Engine size: | 1968 |
| Gear box : | Manueel | Number of places: | 5 |
| Number of gears: | 6 | Number of doors: | 5 |
| HP: | 136 | kW: | 100 |
| Fisc HP | | Imported vehicle: | |
| Animals transported: | No | Smoked in vehicle: | No |
| Due date vehicle inspection: | | Extra set of tires: | No |
| | | Use: | Unknown |
| General condition: | | | |

| | | | | |
|------------------------------|----|-----------------------|-------------------------|--------|
| Original registr. number : | OK | Service manual : | NOK | [x] |
| Cert. of reg. / Part 1: | | Cert. of conformity : | OK | |
| Cert. of reg. copy / Part 2: | OK | [x] | Insurance certificate : | |
| Warning vest : | OK | [x] | Transport licence : | |
| Tax certificate : | | | Navigation CD/SD/DVD | OK [x] |
| Fuel card : | | | Car radio : | OK [x] |
| Mobile phone kit : | | | Extinguisher : | OK [x] |
| First aid kit : | OK | [x] | Warning triangle : | OK [x] |
| Jack, wheelspanner : | | [x] | Oil level : | OK [x] |
| | | | Filled up : | 0 |

Wheels and tyres: Summer tires

| | | | | | | | | | | | | |
|------------|-----|---------|--------|-----|-----|------|-------|-------|-----------------|-----------------|----------|----------|
| Wheel FL: | [x] | PIRELLI | Tyre : | OK | [x] | 2-4/ | Rim : | [x] | WHEEL SCRATCHED | / | Hubcap : | |
| Wheel RL : | [x] | PIRELLI | Tyre : | OK | [x] | 2-4/ | Rim : | [x] | WHEEL SCRATCHED | / | Hubcap : | |
| Wheel FR : | [x] | PIRELLI | Tyre : | [x] | OK | [x] | 2-4/ | Rim : | [x] | WHEEL SCRATCHED | / | Hubcap : |
| Wheel RR : | [x] | PIRELLI | Tyre : | OK | [x] | 2-4/ | Rim : | [x] | WHEEL SCRATCHED | / | Hubcap : | |
| Wheel RES: | [x] | | Tyre : | OK | | / | Rim : | | | / | Hubcap : | |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 225 | 55 | R | 17 | W |
| Rear tyre | 225 | 55 | R | 17 | W |

Remark :

Wheels and tyres:

| | | | | | | | | |
|------------|--|--------|----|---|-------|--|---|----------|
| Wheel FL: | | Tyre : | OK | / | Rim : | | / | Hubcap : |
| Wheel RL : | | Tyre : | OK | / | Rim : | | / | Hubcap : |
| Wheel FR : | | Tyre : | OK | / | Rim : | | / | Hubcap : |
| Wheel RR : | | Tyre : | OK | / | Rim : | | / | Hubcap : |
| Wheel RES: | | Tyre : | OK | / | Rim : | | / | Hubcap : |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0 | 0 | R | 0 | |
| Rear tyre | 0 | 0 | R | 0 | |

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

| | | |
|-----|---------------------------|---------------------------|
| [x] | REAR DOOR/CENTER/RIGHT | DENT |
| [x] | FRONT DOOR/RIGHT/CENTER | SCRATCH WITH PAINT DAMAGE |
| [x] | BONNET/CENTER/RIGHT/FRONT | CHIPS |

Interior

| | | |
|-----|------------|--------|
| [x] | FLOOR FL | HOLE |
| [x] | DOOR IN FL | CARVED |
| [x] | FLOOR BOOT | DIRTY |

STATUS: NOT ACCEPTABLE

Bodywork \& windows

| | | | | | |
|-----|---------------------------|---------------------------|----------------------|--------------|--------------|
| [x] | REAR MUDGUARD/LEFT/CENTER | SCRATCH WITH PAINT DAMAGE | | | |
| | | Repair paint - LI | New paint - E | Depr. | Total |
| 4 | 5 LU =24.00 EUR | 0 EUR | | 50 % | 24.00 EUR |
| [x] | FRONT DOOR/LEFT/FRONT | SCRATCH WITH PAINT DAMAGE | | | |
| | | Repair paint - LI | New paint - E | Depr. | Total |
| 3 | 0 LU =0.00 EUR | 382.02 EUR | | 50 % | 382.02 EUR |
| [x] | FRONT MUDGUARD/LEFT/FRONT | DENT | | | |
| | | Repair paint - LI | New paint - E | Depr. | Total |
| 2 | 0 LU =0.00 EUR | 264.21 EUR | | 50 % | 264.21 EUR |
| [x] | FRONT BUMPER/LEFT | HOLE/CRACK/TORN | | | |
| | | Repair paint - LI | New paint - E | Depr. | Total |
| 1 | 20 LU =96.00 EUR | 0 EUR | 282.96 EUR | 50 % | 378.96 EUR |

Others

RIM FRONT LEFT

| Number | Code | Description | Unit price | Depr. | Total |
|--------|-----------------------|--------------------|------------|-------|-----------|
| 5 | I 1 i-vab-herstalu-02 | REPAIR ALLOY WHEEL | 95.00 EUR | | 95.00 EUR |

RIM REAR LEFT

| Number | Code | Description | Unit price | Depr. | Total |
|--------|------|-------------------|--------------------|-----------|-----------|
| 5 | I 1 | i-vab-herstalu-02 | REPAIR ALLOY WHEEL | 95.00 EUR | 95.00 EUR |

Pieces

| Number | Code | Description | Unit price | Depr. | Total |
|--------|------|--------------|------------|-------|------------|
| 1 | 1 | FRONT BUMPER | 483.84 EUR | 50 % | 483.84 EUR |

| Number | Code | Description | Unit price | Depr. | Total |
|--------|------|-------------|------------|-------|-----------|
| 1 | 1 | INZETSTUK | 25.00 EUR | 50 % | 25.00 EUR |

| Number | Code | Description | Unit price | Depr. | Total |
|--------|------|-------------|------------|-------|-----------|
| 2 | 1 | WHEEL HUL | 72.00 EUR | 50 % | 72.00 EUR |

| Number | Code | Description | Unit price | Depr. | Total |
|--------|------|-------------|------------|-------|-----------|
| 4 | 1 | WHEEL HUL | 72.00 EUR | 50 % | 72.00 EUR |

| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
|--------|--------|--------|-------|--------|---|---|---|---|----|
| 887.80 | 336.21 | 382.02 | 96.00 | 190.00 | 0 | 0 | 0 | 0 | 0 |
| 443.90 | 168.10 | 191.01 | 48.00 | 190.00 | 0 | 0 | 0 | 0 | 0 |

| INNOVATIVE | TRADITIONAL | GENERAL | |
|------------|-------------|---------|----------------------|
| 190.00 | 1702.03 | 0 | 1892.03 |
| HOG: 0 | BG: 2 | | NA Deprec. 1041.02 |
| | | | 0.00% |
| | | | TOTAL 1041.02 |

[x] = Status Modification


Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

| | | |
|---|--|---|
| Extra Time : 0 min | Waiting time : 0 min Reason : | Towing time : 0 min Reason : |
| NOT EXECUTED : No Reason : | | |
| Remark : | | |

Prices in EUR without VAT

| | |
|---|--------------------------------|
| Authorized by customer : Remark authorized customer : Date : 14/11/2017 Hour : 10:29 Company : Executed by VAB Fleet Services E-Mail : @ | Executed by VAB Fleet Services |
| Signature authorized by customer  | |