

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	151545 KM
File nr. :	1455880	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1EPO857 / WAUZZZ8P3DA068129 /		yr of constructionr :	/
E-File nr. :		First registration :	15/02/2013
VFS-nr. :		Color :	
Make + Model :	AUDI / A3	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	KBC VERZEKERINGEN NV	Co2:	102g/km
Driver :		Remote controls:	
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :	A3 SB TDie Attract.Start/Stop DPF 105PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:		Number of doors:	5
HP:	105	kW:	77
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :	OK	[x]	Oil level :	OK [x]
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	195	65	R	15	H
Rear tyre	195	65	R	15	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] REAR BUMPER/CENTER/LEFT SCRATCH (WITHOUT PAINT DAMAGE)
- [x] FRONT DOOR/LEFT/REAR SCRATCH (WITHOUT PAINT DAMAGE)
- [x] WINDSCREEN/CENTER/LEFT CHIPS
- [x] FRONT DOOR/RIGHT/REAR SCRATCH (WITHOUT PAINT DAMAGE)
- [x] BONNET/CENTER/LEFT/FRONT CHIPS
- [x] FRONT BUMPER/CENTER/LEFT CHIPS

Accessories and others

- [x] OUTSIDE MIRROR LEFTHAND SIDE SCRATCH (WITHOUT PAINT DAMAGE)
- [x] OUTSIDE MIRROR RIGHTHAND SIDE SCRATCH WITH PAINT DAMAGE

1	2	3	4	5	6	7	8	9	10
0	0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	0	0	0
HOG: 0	BG: 1		NA Deprec. 0
			0.00%
			TOTAL 0

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 10/11/2017 Hour : 14:14 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	