

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: DIRTY [x]
Owner :		Mileage :	178064 KM
File nr. :	1456545	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DWL121 / WBAMX11030C977050 /		yr of constructionr :	/
E-File nr. :		First registration :	18/09/2012
VFS-nr. :		Color :	BLUE D
Make + Model :	BMW / 5 TOURING	Fuel type :	DIESEL
Object nr. :	77354	Fuel :	
Classification :	L	Environment Class:	EURO 5
Customer company :	UCB PHARMA SA	Co2:	130g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	5 TOURING 520d Start/Stop 163PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1995
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	163	kW:	120
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :	OK	[x]	Oil level :	OK [x]
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK	/		Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	225	55	R	17	V
Rear tyre	225	55	R	17	V

Remark :

Wheels and tyres:

Wheel FL:			Tyre :	OK	/		Rim :	/	Hubcap :
Wheel RL :			Tyre :	OK	/		Rim :	/	Hubcap :
Wheel FR :			Tyre :	OK	/		Rim :	/	Hubcap :
Wheel RR :			Tyre :	OK	/		Rim :	/	Hubcap :
Wheel RES:			Tyre :	OK	/		Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] REAR BUMPER/CENTER/LEFT SCRATCH WITH PAINT DAMAGE
- [x] ROOF/CENTER/RIGHT DENT

STATUS: NOT ACCEPTABLE

Bodywork \& windows

	Repair paint - LI	New paint - E	Depr.	Total
[x] REAR THRESHOLD/LEFT/REAR 2 0 LU =0.00 EUR	372.60 EUR		50 %	372.60 EUR
[x] FRONT DOOR/LEFT/CENTER 3 0 LU =0.00 EUR	382.02 EUR		50 %	382.02 EUR
[x] FRONT BUMPER/RIGHT 1 0 LU =0.00 EUR	254.16 EUR		50 %	254.16 EUR

1	2	3	4	5	6	7	8	9	10
254.16	372.60	382.02	0	0	0	0	0	0	0
127.08	186.30	191.01	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	1008.78	0	1008.78
HOG: 0	BG: 2		NA Deprec. 504.39
			0.00%
			TOTAL 504.39

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - VEHICLE WET

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 13/11/2017 Hour : 15:03 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	