

www.vabfleetservices.be Date: 10/11/2017 1/5

D9EJII

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

Commissionar: KBC REMARKETING Cleanliness: INT: CLEAN [x] EXT: DIRTY [x]

Owner: 198874 KM

File nr.: 1456240 Mileage start / arrival: 0 / 0

Reg number / Chassis / Ref: 0

1DBL645 / WBAMX11050C974988 / yr of constructionr : /

E-File nr.: First registration: 02/04/2012

VFS-nr.: Color: GREY

Make + Model: BMW / 5 Fuel type: DIESEL

Object nr.: 32600 Fuel:

Classification: Environment Class: EURO 5
Customer company: UZ ANTWERPEN VZW Co2: 130g/km

Driver: Remote controls: 2

Covering: LEATHER Number keys: 2 [x]

Vehicle kind : Seats (minivan) : ()

 Vehicle type :
 5 TOURING 520d Start/Stop 184PK
 Country registration :
 BELGIUM

 VAT over the margin - car:
 No
 Metallic paint:

 Variant car:
 BREAK
 Engine size:
 1995

Gear box: Number of places: 5

Number of gears: 6 Number of doors: 5

HP: 184 **kW:** 135

Fisc HP Imported vehicle:

Animals transported: Smoked in vehicle:

Due date vehicle inspection: Extra set of tires:

Use: Unknown

General condition:



Date: 10/11/2017 www.vabfleetservices.be 2/5

Original registr. number :	OK		Se	ervice manual :	OK	[x]
Cert. of reg. / Part 1:			Co	ert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	In	surance certificate :		
Warning vest :	OK	[x]	Tı	ransport licence :		
Tax certificate :			Na	avigation CD/SD/DVD		
Fuel card :			Ca	ar radio :		
Mobile phone kit :			Ez	xtinguisher :	OK	[x]
			w	arning triangle :	OK	[x]
First aid kit :	OK	[x]	Oi	il level :	OK	[x]
Jack, wheelspanner :			Fi	lled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	CONTIN	ENTAL	Tyre:		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED	,	Hubcap:	
Wheel RL:	[x]	CONTIN	ENTAL	Tyre:		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED	,	Hubcap:	
Wheel FR:	[x]	CONTIN	ENTAL	Tyre:	[x]	OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED	,	Hubcap:	
Wheel RR:	[x]	CONTIN	ENTAL	Tyre:		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED	,	Hubcap:	
Wheel RES:	[x]			Tyre:		OK		/	Rim:		/		Hubcap:	
		[x]	W	idth			He	eight			Type		Rim	Index
Fro	nt tyre		2	225				55			R		17	M+S

_	[x]	Width	Height	Туре	Rim	Index
	Front tyre	225	55	R	17	M+S
	Rear tyre	225	55	R	17	M+S

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

	[x]	Width	Height	Type	Rim	Index
Fron	ıt tyre	0	0	R	0	
Rear	r tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 10/11/2017 3/5

STATUS: ACCEPTABLE / USAGE DAMAGE

30	dywork \& windows					
x]	REAR DOOR/CENTER/RIGHT		SCRATCH WITH PA	AINT DAMAGE		
x]	REAR MUDGUARD/RIGHT/FRONT		DENT			
()	FRONT DOOR/LEFT/REAR		SCRATCH WITH PA	AINT DAMAGE		
.]	FRONT DOOR/RIGHT/CENTER		SCRATCH (WITHO	UT PAINT DAMAGE)	
]	FRONT MUDGUARD/RIGHT/REAR		SCRATCH (WITHO	UT PAINT DAMAGE)	
κ]	ROOF/CENTER/LEFT		SCRATCH (WITHO	UT PAINT DAMAGE)	
C	cessories and others					
:]	OUTSIDE MIRROR RIGHTHAND SIDE		SCRATCH WITH PA	AINT DAMAGE		
ST	ATUS: NOT ACCEPTAB	LE				
30	dywork \& windows					
.]	REAR BUMPER/CENTER/LEFT		SCRATCH WITH PA	AINT DAMAGE		
		Repair paint - LI	New paint - E		Depr.	Total
	3 0 LU =0.00 EUR	254.16 EUR	,		50 %	254.16 EUI
]	REAR DOOR/RIGHT/CENTER		DENT			
		Repair paint - LI	New paint - E		Depr.	Total
	4 10 LU =48.00 EUR	382.02 EUR	,		50 %	430.02 EUI
κ]	FRONT BUMPER/RIGHT		SCRATCH WITH PA	AINT DAMAGE		
		Repair paint - LI	New paint - E		Depr.	Total
	2 0 LU =0.00 EUR	254.16 EUR			50 %	254.16 EUI
)tł	ners					
	RIM REAR LEFT					
	Number Code	Description		Unit price	Depr.	Total
	5 I 1 i-vab-herstalu-02	REPAIR ALLOY WH	EEL	95.00 EUR		95.00 EUR
	RIM REAR RIGHT					
		5		TT:4:	D	T-4-1
	Number Code	Description		Unit price	Depr.	Total



www.vabfleetservices.be Date: 10/11/2017 4/5

1	2	3	4	5	6	7	8	9	10
0	254.16	254.16	430.02	190.00	0	0	0	0	0
0	127.08	127.08	215.01	190.00	0	0	0	0	0

		GENERAL	TRADITIONAL	INNOVATIVE
1128.34		0	938.34	190.00
659.17	NA Deprec.		BG: 2	HOG: 0
	0.00%			
659.17	TOTAL			



www.vabfleetservices.be Date: 10/11/2017 5/5

[x] = Status Modification

Pictures: No

CIRCUMS	STANCES		UNDER CONDITION - VEHICLE WET						
Extra Time :	0 min	Waiting time :	0 min	Towing time :	0 min				
		Reason:		Reason:					
NOT EXECUTED	: No								
Reason :									
Remark :	,								
Prices in EUR	without VAT								
Authorized by customer :			Executed by V	/AB Fleet Services					
Remark authorized	l customer :								
Date :	10/11/2017	Hour: 15:13							
Company :									
Executed by VAB I Services	Fleet								
E-Mail :	@								
Signature authorized	1 by customer								
	_								
l									