

APPRAISAL

www.vabfleetservices.be Date: 14/11/2017 1/4

DBPBN0

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

VAT over the margin - car:

No

Commissionar :	KBC REMARKETING	Cleanliness:	INT: DIRTY [x] EXT: DIRTY [x]
Owner:		Mileage :	179376 KM
File nr. :	1458084	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1CRU194 / WBAMX11	0X0DU49239 /	yr of constructionr :	/
E-File nr. :		First registration :	13/02/2012
VFS-nr. :		Color :	GREY
Make + Model :	BMW / 5 TOURING	Fuel type :	DIESEL
Object nr. :	2641	Fuel:	
Classification :		Environment Class:	EURO 5
Customer company :	2-PEOPEL ICT SERVICES BVBA	Co2:	129g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	5 TOURING 520dAS St/St 163PK Aut.	Country registration :	BELGIUM

		•	
Variant car:	BREAK	Engine size:	1995
Gear box :	Automaat algemeen	Number of places:	5
Number of gears:		Number of doors:	5
HP:	163	kW:	120
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Metallic paint:

Yes



APPRAISAL

14/11/2017 Date: www.vabfleetservices.be 2/4

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:			Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD	OK	[x]
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :			Filled up :	0	

Wheels and tyres: Summer tires

lΓ	Fron	t tyre	Î	225				55		R		17	W
			[x]	Width			Н	eight	Ì	Туре		Rim	Index
Wł	neel RES:	[x]		Tyre	:	OK		/	Rim:		/	Hubcap:	
	neel RR:	[x]	MICHI	ELIN Tyre	:	OK	[x]	2-4 /	Rim:		/	Hubcap:	
Wł	neel FR:	[x]	MICHI	ELIN Tyre	: [x]	OK	[x]	2-4 /	Rim:		/	Hubcap:	
Wł	neel RL:	[x]	MICHI	ELIN Tyre	:	OK	[x]	2-4 /	Rim:		/	Hubcap:	
Wł	neel FL:	[x]	MICH	ELIN Tyre	:	OK	[x]	2-4 /	Rim:		/	Hubcap:	

Front tyre 225 55 R 17 W Rear tyre 225 55 R 17 W	[x]	Width	Height	Туре	Rim	Index
Rear tyre 225 55 R 17 W	Front tyre		55	R	17	W
Real tyte 225 55 K	Rear tyre	225	55	R	17	W

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:
_					

_	[x]	Width	Height	Туре	Rim	Index
	Front tyre	0	0	R	0	
	Rear tyre	0	0	R	0	

Remark:



Others

APPRAISAL

www.vabfleetservices.be Date: 14/11/2017 3/4

STATUS: NOT ACCEPTABLE

CLEANLINESS INTERIOR

	Number	Code	Description	Unit price	Depr.	Total
1	I 4	specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR		58.32 EUR

1	2	3	4	5	6	7	8	9	10
58.32	0	0	0	0	0	0	0	0	0
58.32	0	0	0	0	0	0	0	0	0

		GENERAL	TRADITIONAL	INNOVATIVE
58.32		0	0	58.32
58.32	NA Deprec.		BG: 2	HOG: 0
	0.00%			
58.32	TOTAL			



APPRAISAL

4/4

14/11/2017 www.vabfleetservices.be Date: [x] = Status Modification **Pictures:** No **CIRCUMSTANCES** NORMAL CONCLUSION Extra Time : $0 \min$ Waiting time: 0 min Towing time : $0 \min$ Reason: Reason: NOT EXECUTED: No Reason: Remark: Prices in EUR without VAT Authorized by Executed by VAB Fleet Services customer : Remark authorized customer : Date: 14/11/2017 Hour: Company: Executed by VAB Fleet Services E-Mail: Signature authorized by customer