

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

| | | | |
|-------------------------------------|----------------------------|---------------------------------|-------------------------------|
| Commissionar : | KBC REMARKETING | Cleanliness : | INT: CLEAN [x] EXT: CLEAN [x] |
| Owner : | | Mileage : | 32779 KM |
| File nr. : | 1458331 | Mileage start / arrival: | 0 / 0 |
| Reg number / Chassis / Ref : | | Mileag ref. service : | 0 |
| 1HZV991 / VF7SA8HR4EW658303 / | | yr of constructionr : | / |
| E-File nr. : | | First registration : | 12/11/2014 |
| VFS-nr. : | | Color : | GREY |
| Make + Model : | CITROEN / DS3 | Fuel type : | DIESEL |
| Object nr. : | 50683 | Fuel : | |
| Classification : | A | Environment Class: | EURO 5 |
| Customer company : | 2-PEOPEL ICT SERVICES BVBA | Co2: | 99g/km |
| Driver : | | Remote controls: | 1 |
| Covering : | TISSUE | Number keys : | 2 [x] |
| Vehicle kind : | | Seats (minivan) : | 0 |
| Vehicle type : | | Country registration : | BELGIUM |

| | | | |
|-------------------------------------|---------|----------------------------|---------|
| VAT over the margin - car: | | Metallic paint: | Yes |
| Variant car: | | Engine size: | 1398 |
| Gear box : | Manueel | Number of places: | 5 |
| Number of gears: | 5 | Number of doors: | 3 |
| HP: | 68 | kW: | 50 |
| Fisc HP | | Imported vehicle: | |
| Animals transported: | | Smoked in vehicle: | No |
| Due date vehicle inspection: | | Extra set of tires: | No |
| | | Use: | Unknown |
| General condition: | | | |

| | |
|--------------------------------|---------------------------|
| Original registr. number : OK | Service manual : OK [x] |
| Cert. of reg. / Part 1: OK [x] | Cert. of conformity : OK |
| Cert. of reg. copy / Part 2: | Insurance certificate : |
| Warning vest : | Transport licence : |
| Tax certificate : | Navigation CD/SD/DVD |
| Fuel card : | Car radio : OK [x] |
| Mobile phone kit : | Extinguisher : |
| First aid kit : | Warning triangle : OK [x] |
| Jack, wheelspanner : OK [x] | Oil level : OK [x] |
| | Filled up : 0 |

Wheels and tyres: Summer tires

| |
|---|
| Wheel FL: [x] MICHELIN Tyre : OK [x] 4-6/ Rim : / Hubcap : |
| Wheel RL : [x] MICHELIN Tyre : OK [x] 4-6/ Rim : [x] WHEEL SCRATCHED / Hubcap : |
| Wheel FR : [x] MICHELIN Tyre : [x] OK [x] 4-6/ Rim : [x] WHEEL SCRATCHED / Hubcap : |
| Wheel RR : [x] MICHELIN Tyre : OK [x] 4-6/ Rim : [x] WHEEL SCRATCHED / Hubcap : |
| Wheel RES: [x] ANDERE Tyre : OK [x] >6/ Rim : / Hubcap : |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 195 | 55 | R | 16 | T |
| Rear tyre | 195 | 55 | R | 16 | T |

Remark :

Wheels and tyres:

| |
|---|
| Wheel FL: Tyre : OK / Rim : / Hubcap : |
| Wheel RL : Tyre : OK / Rim : / Hubcap : |
| Wheel FR : Tyre : OK / Rim : / Hubcap : |
| Wheel RR : Tyre : OK / Rim : / Hubcap : |
| Wheel RES: Tyre : OK / Rim : / Hubcap : |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0 | 0 | R | 0 | |
| Rear tyre | 0 | 0 | R | 0 | |

Remark :

STATUS: NOT ACCEPTABLE

Bodywork \& windows

| | | | | | | | | |
|-----|---------------------------|---------------|--------------------------|----------------------|--------------|--------------|--|--|
| [x] | REAR MUDGUARD/LEFT/CENTER | | DENT | | | | | |
| | Number | Code | Description | Unit price | Depr. | Total | | |
| 3 | I 1 | i-vab-uitd-01 | BEAT OUT DENT | 63.00 EUR | | 63.00 EUR | | |
| | Number | Code | Description | Unit price | Depr. | Total | | |
| 3 | I 1 | i-vab-uitd-02 | BEAT OUT DENT SUPPL | 19.80 EUR | | 19.80 EUR | | |
| [x] | FRONT DOOR/LEFT/REAR | | DENT | | | | | |
| | Number | Code | Description | Unit price | Depr. | Total | | |
| 2 | I 1 | i-vab-uitd-01 | BEAT OUT DENT | 63.00 EUR | | 63.00 EUR | | |
| | Number | Code | Description | Unit price | Depr. | Total | | |
| 2 | I 1 | i-vab-uitd-02 | BEAT OUT DENT SUPPL | 19.80 EUR | | 19.80 EUR | | |
| [x] | BONNET/CENTER/LEFT | | HOLE/CRACK/TORN | | | | | |
| | | | Repair paint - LI | New paint - E | Depr. | Total | | |
| 1 | 5 LU | =24.00 EUR | 0 EUR | | 50 % | 24.00 EUR | | |

Others

| | | | | | | | | |
|-----------------|---------------|-------------------|--------------------|-------------------|--------------|--------------|--|--|
| RIM REAR LEFT | | | | | | | | |
| | Number | Code | Description | Unit price | Depr. | Total | | |
| 4 | I 1 | i-vab-herstalu-02 | REPAIR ALLOY WHEEL | 95.00 EUR | | 95.00 EUR | | |
| RIM REAR RIGHT | | | | | | | | |
| | Number | Code | Description | Unit price | Depr. | Total | | |
| 4 | I 1 | i-vab-herstalu-02 | REPAIR ALLOY WHEEL | 95.00 EUR | | 95.00 EUR | | |
| RIM FRONT RIGHT | | | | | | | | |
| | Number | Code | Description | Unit price | Depr. | Total | | |
| 4 | I 1 | i-vab-herstalu-02 | REPAIR ALLOY WHEEL | 95.00 EUR | | 95.00 EUR | | |

Pieces

| | | | | | | | | |
|---|---------------|-------------|--------------------|-------------------|--------------|--------------|--|--|
| | Number | Code | Description | Unit price | Depr. | Total | | |
| 1 | 1 | ISOLATIE | | 30.00 EUR | 50 % | 30.00 EUR | | |

| | | | | | | | | | |
|-------|-------|-------|--------|---|---|---|---|---|----|
| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
| 54.00 | 82.80 | 82.80 | 285.00 | 0 | 0 | 0 | 0 | 0 | 0 |
| 27.00 | 82.80 | 82.80 | 285.00 | 0 | 0 | 0 | 0 | 0 | 0 |

| INNOVATIVE | TRADITIONAL | GENERAL | |
|------------|-------------|---------|---------------------|
| 450.60 | 54.00 | 0 | 504.60 |
| HOG: 0 | BG: 1 | | NA Deprec. 477.60 |
| | | | 0.00% |
| | | | TOTAL 477.60 |

[x] = Status Modification


Pictures : No

CIRCUMSTANCES

UNDER CONDITION - DARK

| | | |
|---|--|---|
| Extra Time : 0 min | Waiting time : 0 min Reason : | Towing time : 0 min Reason : |
| NOT EXECUTED : No Reason : | | |
| Remark : | | |

Prices in EUR without VAT

| | |
|---|--------------------------------|
| Authorized by customer : Remark authorized customer : Date : 15/11/2017 Hour : 14:43 Company : Executed by VAB Fleet Services E-Mail : @ | Executed by VAB Fleet Services |
| Signature authorized by customer  | |