

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	90259 KM
File nr. :	1455492	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1CCW664 / VF7YDUMGC12074802 /		yr of constructionr :	/
E-File nr. :		First registration :	21/10/2011
VFS-nr. :		Color :	WHITE
Make + Model :	CITROEN / JUMPER	Fuel type :	DIESEL
Object nr. :	53721	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	ESPACES ASBL	Co2:	229g/km
Driver :		Remote controls:	0
Covering :	IMITATION LEATHER	Number keys :	1 [x]
Vehicle kind :	TRUCK, LORRY	Seats (minivan) :	0
Vehicle type :	JUMPER 35+ PL2C LWB L3 150PK FAP (EU5)	Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	BESTELWAGEN	Engine size:	2198
Gear box :	Manueel	Number of places:	7
Number of gears:	6	Number of doors:	4
HP:	150	kW:	110
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :			Oil level :	OK [x]
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :	
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :	
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	>6/	Rim :	/	Hubcap :
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	225	75	R	16	
Rear tyre	225	75	R	16	

Remark :

Wheels and tyres:

Wheel FL:			Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :			Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :			Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :			Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:			Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Interior

[x] SEAT FL OTHER DAMAGES

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] REAR MUDGUARD/RIGHT/CENTER SCRATCH WITH PAINT DAMAGE

Number	Code	Description	Unit price	Depr.	Total
5	I 1 i-vab-sp-02	2ND SPOTREPAIR SAME PART	51.00 EUR	50 %	51.00 EUR

[x] REAR THRESHOLD/LEFT/FRONT SCRATCH WITH PAINT DAMAGE

Number	Code	Description	Unit price	Depr.	Total
0	0				

[x] REAR THRESHOLD/RIGHT/REAR SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
6 0 LU =0.00 EUR	232.88 EUR		50 %	232.88 EUR

[x] THRESHOLD FRONT/LEFT/CENTER SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
4 0 LU =0.00 EUR	0 EUR		50 %	

[x] FRONT MUDGUARD/LEFT/REAR SCRATCH WITH PAINT DAMAGE

Number	Code	Description	Unit price	Depr.	Total
3	I 1 i-vab-kunst-01	PLASTICS REPAIR	110.64 EUR		110.64 EUR

[x] FRONT BUMPER/LEFT/CORNER SCRATCH WITH PAINT DAMAGE

Number	Code	Description	Unit price	Depr.	Total
0	0				

[x] FRONT BUMPER/RIGHT/CORNER SCRATCH WITH PAINT DAMAGE

Number	Code	Description	Unit price	Depr.	Total
2	I 1 i-vab-kunst-01	PLASTICS REPAIR	110.64 EUR		110.64 EUR

Interior

[x] DOOR IN REAR L OTHER DAMAGES

	Repair paint - LI	New paint - E	Depr.	Total
7 0 LU =0.00 EUR	0 EUR			

[x] DOOR IN REAR RIGHT

OTHER DAMAGES

	Repair paint - LI	New paint - E	Depr.	Total
7 0 LU =0.00 EUR	0 EUR		50 %	

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 5	bestelwagen-cabine-a-vab-rein-05	CLEANING INTERIOR	11.47 EUR	57.35 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
7	1	PLAATJE	10.00 EUR		10.00 EUR
7	1	2 PLAATJES	20.00 EUR	50 %	20.00 EUR

1	2	3	4	5	6	7	8	9	10
57.35	110.64	110.64	0.00	51.00	232.88	30.00	0	0	0
57.35	110.64	110.64	0.00	25.50	116.44	20.00	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
329.63	262.88	0	592.51
HOG: 0	BG: 3		NA Deprec. 440.57
			0.00%
			TOTAL 440.57

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 13/11/2017 Hour : Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	