

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: DIRTY [x]
Owner :		Mileage :	153187 KM
File nr. :	1457120	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
870APV / VF77D9HSC9J098926 /		yr of constructionr :	/
E-File nr. :		First registration :	02/06/2009
VFS-nr. :		Color :	GREY
Make + Model :	CITROEN / BERLINGO	Fuel type :	DIESEL
Object nr. :	11065	Fuel :	
Classification :		Environment Class:	EURO 4
Customer company :	AQUAFIN NV	Co2:	g/km
Driver :		Remote controls:	1
Covering :	IMITATION LEATHER	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :	BERLINGO B/F PLC Court/Kort FAP 90PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BESTELWAGEN	Engine size:	1560
Gear box :	Manueel	Number of places:	
Number of gears:	5	Number of doors:	5
HP:	90	kW:	66
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number : OK	Service manual : OK [x]
Cert. of reg. / Part 1:	Cert. of conformity : OK
Cert. of reg. copy / Part 2: OK [x]	Insurance certificate :
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher : OK [x]
First aid kit : OK [x]	Warning triangle : OK [x]
Jack, wheelspanner : OK [x]	Oil level : OK [x]
	Filled up : 0

Wheels and tyres: Summer tires

Wheel FL: [x] MICHELIN Tyre : OK [x] 4-6/ Rim : / Hubcap : [x] SCRATCHED
Wheel RL : [x] MICHELIN Tyre : OK [x] 4-6/ Rim : / Hubcap : [x] SCRATCHED
Wheel FR : [x] MICHELIN Tyre : [x] OK [x] 4-6/ Rim : / Hubcap : [x] MISSING/INCOMPLETE
Wheel RR : [x] MICHELIN Tyre : OK [x] 4-6/ Rim : / Hubcap : [x] SCRATCHED
Wheel RES: [x] MICHELIN Tyre : OK [x] >6/ Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	195	65	R	15	V
Rear tyre	195	65	R	15	V

Remark :

Wheels and tyres:

Wheel FL: Tyre : OK / Rim : / Hubcap :
Wheel RL : Tyre : OK / Rim : / Hubcap :
Wheel FR : Tyre : OK / Rim : / Hubcap :
Wheel RR : Tyre : OK / Rim : / Hubcap :
Wheel RES: Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] REAR MUDGUARD/LEFT/FRONT DENT
- [x] REAR MUDGUARD/RIGHT/CENTER SCRATCH (WITHOUT PAINT DAMAGE)

Interior

- [x] STEERING WHEEL OTHER DAMAGES
- [x] SEAT FL OTHER DAMAGES
- [x] BOOT LID IN OTHER DAMAGES

Accessories and others

- [x] OUTSIDE MIRROR SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

- [x] REAR BUMPER/SIDE/LEFT/FRONT OTHER DAMAGES

Number	Code	Description	Unit price	Depr.	Total
2	I 1 i-vab-ander-01	REPAIR (PER 15')	18.74 EUR		18.74 EUR

- [x] ROOF/REAR/LEFT DENT

	Repair paint - LI	New paint - E	Depr.	Total
4 0 LU =0.00 EUR	361.13 EUR		50 %	361.13 EUR

- [x] REAR DOOR/RIGHT/CENTER SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
3 0 LU =0.00 EUR	238.76 EUR		50 %	238.76 EUR

- [x] THRESHOLD FRONT/LEFT/CENTER DENT

	Repair paint - LI	New paint - E	Depr.	Total
1 40 LU =192.00 EUR	0 EUR	310.50 EUR	50 %	502.50 EUR

- [x] FRONT BUMPER/RIGHT/SIDE OTHER DAMAGES ONGEVALSCHADE_OVBH

Number	Code	Description	Unit price	Depr.	Total
0	0				

Others

HUB CAP FL

	Repair paint - LI	New paint - E	Depr.	Total
5 0 LU =0.00 EUR			50 %	

HUB CAP FR

	Repair paint - LI	New paint - E	Depr.	Total
5 0 LU =0.00 EUR			50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	DOORSTEP	187.50 EUR	50 %	187.50 EUR

Number	Code	Description	Unit price	Depr.	Total
5	1	WHEEL CAP	22.50 EUR	50 %	22.50 EUR

Number	Code	Description	Unit price	Depr.	Total
5	1	WHEEL CAP	22.50 EUR	50 %	22.50 EUR

1	2	3	4	5	6	7	8	9	10
690.00	18.74	238.76	361.13	45.00	0	0	0	0	0
345.00	18.74	119.38	180.56	22.50	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
18.74	1334.89	0	1353.63
HOG: 0	BG: 3		NA Deprec. 686.18
			0.00%
			TOTAL 686.18

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark : ONGEVALSCHADE OVBH VERDERE AFHANDELING [x]		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 14/11/2017 Hour : 13:51 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	