

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

| | | | |
|-------------------------------------|---------------------------------------|---------------------------------|-------------------------------|
| Commissionar : | KBC REMARKETING | Cleanliness : | INT: CLEAN [x] EXT: CLEAN [x] |
| Owner : | | Mileage : | 203371 KM |
| File nr. : | 1457636 | Mileage start / arrival: | 0 / 0 |
| Reg number / Chassis / Ref : | | Mileag ref. service : | 0 |
| 1GCS499 / VF73AAHXMDJ859189 / | | yr of constructionr : | / |
| E-File nr. : | | First registration : | 02/01/2014 |
| VFS-nr. : | | Color : | GREY |
| Make + Model : | CITROEN / C4 PICASSO | Fuel type : | DIESEL |
| Object nr. : | 42079 | Fuel : | |
| Classification : | | Environment Class: | EURO 6 |
| Customer company : | MOULINSART SA | Co2: | 110g/km |
| Driver : | | Remote controls: | 2 |
| Covering : | LEATHER | Number keys : | 2 [x] |
| Vehicle kind : | | Seats (minivan) : | 0 |
| Vehicle type : | GR.C4 PICASSO BlueHDi Exclusive 150PK | Country registration : | BELGIUM |

| | | | |
|-------------------------------------|------------|----------------------------|---------|
| VAT over the margin - car: | No | Metallic paint: | Yes |
| Variant car: | MONOVOLUME | Engine size: | 1997 |
| Gear box : | Manueel | Number of places: | 7 |
| Number of gears: | 6 | Number of doors: | 5 |
| HP: | 150 | kW: | 110 |
| Fisc HP | | Imported vehicle: | No |
| Animals transported: | No | Smoked in vehicle: | No |
| Due date vehicle inspection: | | Extra set of tires: | No |
| | | Use: | Unknown |

General condition:

| | | | | |
|------------------------------|----|-------------------------|-----------------------|-----|
| Original registr. number : | OK | Service manual : | OK | [x] |
| Cert. of reg. / Part 1: | OK | [x] | Cert. of conformity : | OK |
| Cert. of reg. copy / Part 2: | | Insurance certificate : | | |
| Warning vest : | | Transport licence : | | |
| Tax certificate : | | Navigation CD/SD/DVD | | |
| Fuel card : | | Car radio : | OK | [x] |
| Mobile phone kit : | | Extinguisher : | OK | [x] |
| First aid kit : | OK | [x] | Warning triangle : | OK |
| Jack, wheelspanner : | OK | [x] | Oil level : | OK |
| | | | Filled up : | 0 |

Wheels and tyres: Summer tires

| | | | | | | | | | | | | |
|------------|-----|----------|--------|-----|-----|------|-------|-------|-----------------|-----------------|----------|----------|
| Wheel FL: | [x] | UNIROYAL | Tyre : | OK | [x] | >6/ | Rim : | [x] | WHEEL SCRATCHED | / | Hubcap : | |
| Wheel RL : | [x] | MICHELIN | Tyre : | OK | [x] | 2-4/ | Rim : | [x] | WHEEL SCRATCHED | / | Hubcap : | |
| Wheel FR : | [x] | UNIROYAL | Tyre : | [x] | OK | [x] | >6/ | Rim : | [x] | WHEEL SCRATCHED | / | Hubcap : |
| Wheel RR : | [x] | MICHELIN | Tyre : | OK | [x] | 2-4/ | Rim : | [x] | WHEEL SCRATCHED | / | Hubcap : | |
| Wheel RES: | [x] | | Tyre : | OK | | / | Rim : | | | / | Hubcap : | |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 205 | 55 | R | 17 | V |
| Rear tyre | 205 | 55 | R | 17 | V |

Remark :

Wheels and tyres:

| | | | | | | | | |
|------------|--|--------|----|---|-------|--|---|----------|
| Wheel FL: | | Tyre : | OK | / | Rim : | | / | Hubcap : |
| Wheel RL : | | Tyre : | OK | / | Rim : | | / | Hubcap : |
| Wheel FR : | | Tyre : | OK | / | Rim : | | / | Hubcap : |
| Wheel RR : | | Tyre : | OK | / | Rim : | | / | Hubcap : |
| Wheel RES: | | Tyre : | OK | / | Rim : | | / | Hubcap : |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0 | 0 | R | 0 | |
| Rear tyre | 0 | 0 | R | 0 | |

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

| | | |
|-----|---------------------------|---------------------------|
| [x] | REAR MUDGUARD/LEFT/CENTER | SCRATCH WITH PAINT DAMAGE |
| [x] | REAR MUDGUARD/RIGHT/FRONT | DENT |
| [x] | REAR DOOR/LEFT/REAR | SCRATCH WITH PAINT DAMAGE |
| [x] | ROOF/REAR/LEFT | SCRATCH WITH PAINT DAMAGE |
| [x] | REAR DOOR/RIGHT/FRONT | DENT |
| [x] | FRONT DOOR/RIGHT/CENTER | SCRATCH WITH PAINT DAMAGE |

Interior

| | | |
|-----|-------------|-----------|
| [x] | BOOT LID IN | SCRATCHED |
|-----|-------------|-----------|

STATUS: NOT ACCEPTABLE

Bodywork \& windows

| | | | | | | |
|-----|---------------------------|-----------------|--------------------------|----------------------|--------------|--------------|
| [x] | REAR BUMPER/RIGHT/RIGHT | HOLE/CRACK/TORN | | | | |
| | | | Repair paint - LI | New paint - E | Depr. | Total |
| 4 | 15 LU =72.00 EUR | 0 EUR | 235.80 EUR | 50 % | 307.80 EUR | |
| [x] | REAR DOOR/LEFT/CENTER | DENT | | | | |
| | | | Unit price | Depr. | Total | |
| 3 | I 1 i-vab-uitd-01 | BEAT OUT DENT | 63.00 EUR | | 63.00 EUR | |
| [x] | FRONT BUMPER/CENTER/RIGHT | DENT | | | | |
| | | | Repair paint - LI | New paint - E | Depr. | Total |
| 2 | 15 LU =72.00 EUR | 211.80 EUR | 50 % | 283.80 EUR | | |

Interior

| | | | | | | |
|-----|----------------|--------------------|--------------------------|----------------------|--------------|--------------|
| [x] | LUGGAGE COVER | MISSING/INCOMPLETE | | | | |
| | | | Repair paint - LI | New paint - E | Depr. | Total |
| 1 | 0 LU =0.00 EUR | 0 EUR | 50 % | | | |

Accessories and others

| | | | | | | |
|-----|----------------|------------------|--------------------------|----------------------|--------------|--------------|
| [x] | ANTENNA | BROKEN / CRACKED | | | | |
| | | | Repair paint - LI | New paint - E | Depr. | Total |
| 1 | 0 LU =0.00 EUR | 0 EUR | 50 % | | | |

Others

RIM FRONT LEFT

| Number | Code | Description | Unit price | Depr. | Total |
|--------|------|-------------------|--------------------|-----------|-----------|
| 5 | I 1 | i-vab-herstalu-02 | REPAIR ALLOY WHEEL | 95.00 EUR | 95.00 EUR |

RIM REAR LEFT

| Number | Code | Description | Unit price | Depr. | Total |
|--------|------|-------------------|--------------------|-----------|-----------|
| 5 | I 1 | i-vab-herstalu-02 | REPAIR ALLOY WHEEL | 95.00 EUR | 95.00 EUR |

RIM REAR RIGHT

| Number | Code | Description | Unit price | Depr. | Total |
|--------|------|-------------------|--------------------|-----------|-----------|
| 5 | I 1 | i-vab-herstalu-02 | REPAIR ALLOY WHEEL | 95.00 EUR | 95.00 EUR |

RIM FRONT RIGHT

| Number | Code | Description | Unit price | Depr. | Total |
|--------|------|-------------------|--------------------|-----------|-----------|
| 5 | I 1 | i-vab-herstalu-02 | REPAIR ALLOY WHEEL | 95.00 EUR | 95.00 EUR |

Pieces

| Number | Code | Description | Unit price | Depr. | Total |
|--------|------|-------------|------------|-------|-----------|
| 1 | 1 | KNOP | 25.00 EUR | 50 % | 25.00 EUR |

| Number | Code | Description | Unit price | Depr. | Total |
|--------|------|-------------|------------|-------|-----------|
| 1 | 1 | ANTENNE | 15.00 EUR | 50 % | 15.00 EUR |

| Number | Code | Description | Unit price | Depr. | Total |
|--------|------|-------------|------------|-------|-----------|
| 2 | 1 | FRONT | 90.00 EUR | 50 % | 90.00 EUR |

| Number | Code | Description | Unit price | Depr. | Total |
|--------|------|-------------|------------|-------|------------|
| 4 | 1 | REAR BUMPER | 343.20 EUR | 50 % | 343.20 EUR |

| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
|-------|--------|-------|--------|--------|---|---|---|---|----|
| 40.00 | 373.80 | 63.00 | 651.00 | 380.00 | 0 | 0 | 0 | 0 | 0 |
| 20.00 | 186.90 | 63.00 | 325.50 | 380.00 | 0 | 0 | 0 | 0 | 0 |

| INNOVATIVE | TRADITIONAL | GENERAL | |
|------------|-------------|---------|---------------------|
| 443.00 | 1064.80 | 0 | 1507.80 |
| HOG: 0 | BG: 0 | | NA Deprec. 975.40 |
| | | | 0.00% |
| | | | TOTAL 975.40 |

[x] = Status Modification


Pictures : No

CIRCUMSTANCES

UNDER CONDITION - VEHICLE WET

| | | |
|---------------------------------------------|------------------------------------------------|-----------------------------------------------|
| Extra Time : 0 min | Waiting time : 0 min Reason : | Towing time : 0 min Reason : |
| NOT EXECUTED : No Reason : | | |
| Remark : | | |

Prices in EUR without VAT

| | |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------|
| Authorized by customer : Remark authorized customer : Date : 14/11/2017 Hour : 15:10 Company : Executed by VAB Fleet Services E-Mail : @ | Executed by VAB Fleet Services |
| Signature authorized by customer  | |