

D20XWH

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: VERY DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	236602 KM
File nr. :	1450404	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1CQK125 / UU1HSDACN46840059 /		yr of constructionr :	/
E-File nr. :		First registration :	02/02/2012
VFS-nr. :		Color :	BLACK
Make + Model :	DACIA / DUSTER	Fuel type :	DIESEL
Object nr. :	47822	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	DALKIA SA<ID>2229924</ID>	Co2:	137g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	1 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	DUSTER 4x4 Laureate FAP 109PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	SUV	Engine size:	1461
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	5
HP:	110	kW:	81
Fisc HP		Imported vehicle:	
Animals transported:	Yes	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	NOK	[x]
Cert. of reg. / Part 1:	[x]	Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :	OK	[x]	Oil level :	OK [x]
		Filled up :	0	

Wheels and tyres: Winter tires

Wheel FL:	[x]	CONTINENTAL	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RL :	[x]	CONTINENTAL	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel FR :	[x]	CONTINENTAL	Tyre :	[x]	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	[x]	CONTINENTAL	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :			/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	215	65	R	16	M+S
Rear tyre	215	65	R	16	M+S

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE
[x]	REAR MUDGUARD/LEFT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	REAR MUDGUARD/RIGHT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	REAR DOOR/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE
[x]	FRONT DOOR/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR DOOR/CENTER/LEFT	DENT				
	Number	Code	Description	Unit price	Depr.	Total
	4	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
[x]	REAR DOOR/LEFT/CENTER	DENT				
			Repair paint - LI	New paint - E	Depr.	Total
	3	0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR
[x]	FRONT DOOR/LEFT/CENTER	DENT				
			Repair paint - LI	New paint - E	Depr.	Total
	3	0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR
[x]	BONNET/CENTER/RIGHT	OTHER DAMAGES			CHEMISCHE INWERKING	
			Repair paint - LI	New paint - E	Depr.	Total
	2	0 LU =0.00 EUR	290.08 EUR		50 %	290.08 EUR
[x]	ROOF/CENTER/LEFT	DENT			CHEMISCHE INWERKING	
			Repair paint - LI	New paint - E	Depr.	Total
	2	0 LU =0.00 EUR	481.50 EUR		50 %	481.50 EUR

Interior

[x]	LUGGAGE COVER	MISSING/INCOMPLETE				
			Repair paint - LI	New paint - E	Depr.	Total
	1	0 LU =0.00 EUR	0 EUR		50 %	

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 6	specifiek-per-kwartier-a-vab-rein-03 CLEANING INTERIOR	14.58 EUR		87.48 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	LUGGAGE COVER	240.00 EUR	50 %	240.00 EUR

1	2	3	4	5	6	7	8	9	10
327.48	771.58	636.70	63.00	0	0	0	0	0	0
207.48	385.79	318.35	63.00	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
150.48	1648.28	0	1798.76
HOG: 0	BG: 0		NA Deprec. 974.62
			0.00%
			TOTAL 974.62

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 13/11/2017 Hour : 10:08 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	