

www.vabfleetservices.be Date: 15/11/2017 1/4

DCQC1C

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

VAT over the margin - car:

No

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner:		Mileage :	186898 KM
File nr. :	1458897	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FPQ767 / WBAVN71070VX	07868 /	yr of constructionr :	/
E-File nr. :		First registration :	17/09/2013
VFS-nr. :		Color :	BROWN
Make + Model :	BMW / X1	Fuel type :	DIESEL
Object nr. :	15844	Fuel:	
Classification:		Environment Class:	EURO 5
Customer company :	COMPUTER TASK GROUP BELGIUM NV	Co2:	128g/km
Driver :		Remote controls:	2
Covering:	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	X1 sDrive18 136PK	Country registration :	BELGIUM

Variant car:	SUV	Engine size:	1995
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
нр:	136	kW:	100
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:		1	

Metallic paint:

Yes



www.vabfleetservices.be Date: 15/11/2017 2/4

Original registr. number :	OK		Service manual :		
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:			Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD	OK	[x]
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :			Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	PIREL	LI	Tyre:		OK	[x]	4-6 /	Rim:	[x]	WHEEL SCRATCHED)	/ Hubcap:	
Wheel RL:	[x]	CONT	INENTAL	Tyre:		OK	[x]	4-6/	Rim:	[x]	WHEEL SCRATCHED)	/ Hubcap:	
Wheel FR:	[x]	PIREL	LI	Tyre:	[x]	OK	[x]	4-6 /	Rim:				/ Hubcap:	
Wheel RR:	[x]	CONT	INENTAL	Tyre:		OK	[x]	4-6 /	Rim:				/ Hubcap:	
Wheel RES:	[x]			Tyre:		OK		/	Rim:				/ Hubcap:	
		[x]	W	idth			Н	eight			Туре		Rim	Index
Fron	t tyre		2	25				50			R		17	W
Real	r tyro		2	25				50			R		17	W

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

[x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 15/11/2017 3/4

STATUS: ACCEPTABLE / USAGE DAMAGE

В	od	yw	ork	\&	wind	lows	
---	----	----	-----	----	------	------	--

[x] REAR BUMPER/CENTER/LEFT SCRATCH WITH PAINT DAMAGE

[x] REAR MUDGUARD/LEFT/REAR DENT

[x] FRONT DOOR/LEFT/CENTER SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] REAR DOOR/RIGHT/FRONT DENT

1	Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR

Others

RIM FRONT LEFT

]	Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM REAR LEFT

	Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

	1	2	3	4	5	6	7	8	9	10
	190.00	63.00	0	0	0	0	0	0	0	0
ſ	190.00	63.00	0	0	0	0	0	0	0	0

	GENERAL	TRADITIONAL	INNOVATIVE
253.00	0	0	253.00
NA Deprec. 253.00		BG: 0	HOG: 0
0.00%	-		

TOTAL 253.00



www.vabfleetservices.be Date: 15/11/2017 4/4

[x] = Status Modification

Pictures: No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time :	0 min	Waiting time: 0 min		Towing time :	0 min
		Reason:		Reason:	
NOT EXECUTED:	No	<u>'</u>			
Reason :					
Remark:					
<u> </u>					
Prices in EUR without VAT					
Authorized by customer:			Executed by VAB Fleet Se	rvices	
customer.					
Remark authorized customer :					
Date :	15/11/2017	Hour:			
Company :					
Executed by VAB Fleet Services					
E-Mail :	@				
Signature authorized by customer					
×			 		