

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

| | | | |
|-------------------------------------|------------------------------------|---------------------------------|-------------------------------|
| Commissionar : | KBC REMARKETING | Cleanliness : | INT: CLEAN [x] EXT: CLEAN [x] |
| Owner : | | Mileage : | 64887 KM |
| File nr. : | 1455946 | Mileage start / arrival: | 0 / 0 |
| Reg number / Chassis / Ref : | | Mileag ref. service : | 0 |
| 1FEQ234 / WF0KXXGCBKDB65202 / | | yr of constructionr : | / |
| E-File nr. : | | First registration : | 07/06/2013 |
| VFS-nr. : | | Color : | BLUE D |
| Make + Model : | FORD / FOCUS | Fuel type : | DIESEL |
| Object nr. : | | Fuel : | |
| Classification : | | Environment Class: | EURO 5 |
| Customer company : | WIRELESS TECHNOLOGIES BVBA | Co2: | 88g/km |
| Driver : | | Remote controls: | 1 |
| Covering : | TISSUE | Number keys : | 1 [x] |
| Vehicle kind : | | Seats (minivan) : | 0 |
| Vehicle type : | FOCUS BER EConetic Trend 88g 105PK | Country registration : | BELGIUM |

| | | | |
|-------------------------------------|---------|----------------------------|---------|
| VAT over the margin - car: | No | Metallic paint: | Yes |
| Variant car: | | Engine size: | 1560 |
| Gear box : | Manueel | Number of places: | 5 |
| Number of gears: | 6 | Number of doors: | 5 |
| HP: | 105 | kW: | 77 |
| Fisc HP | | Imported vehicle: | |
| Animals transported: | | Smoked in vehicle: | |
| Due date vehicle inspection: | | Extra set of tires: | No |
| | | Use: | Unknown |
| General condition: | | | |

| | | | | |
|------------------------------|----|-----------------------|-------------------------|--------|
| Original registr. number : | OK | Service manual : | OK | [x] |
| Cert. of reg. / Part 1: | | Cert. of conformity : | OK | |
| Cert. of reg. copy / Part 2: | OK | [x] | Insurance certificate : | |
| Warning vest : | OK | [x] | Transport licence : | |
| Tax certificate : | | | Navigation CD/SD/DVD | OK [x] |
| Fuel card : | | | Car radio : | OK [x] |
| Mobile phone kit : | | | Extinguisher : | OK [x] |
| First aid kit : | OK | [x] | Warning triangle : | OK [x] |
| Jack, wheelspanner : | | | Oil level : | OK [x] |
| | | | Filled up : | 0 |

Wheels and tyres: Summer tires

| | | | | | | | | | |
|------------|-----|----------|--------|-----|-----|--------|--------|--------------------------|--------------------------|
| Wheel FL: | [x] | MICHELIN | Tyre : | OK | [x] | 1.6-2/ | Rim : | / | Hubcap : |
| Wheel RL : | [x] | MICHELIN | Tyre : | OK | [x] | 2-4/ | Rim : | / | Hubcap : |
| Wheel FR : | [x] | MICHELIN | Tyre : | [x] | OK | [x] | 1.6-2/ | Rim : | / Hubcap : [x] SCRATCHED |
| Wheel RR : | [x] | MICHELIN | Tyre : | OK | [x] | 2-4/ | Rim : | / Hubcap : [x] SCRATCHED | |
| Wheel RES: | [x] | MICHELIN | Tyre : | OK | [x] | >6/ | Rim : | / Hubcap : | |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 205 | 55 | R | 16 | H |
| Rear tyre | 205 | 55 | R | 16 | H |

Remark :

Wheels and tyres:

| | | | | | | | |
|------------|--|--------|----|---|-------|---|----------|
| Wheel FL: | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RL : | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel FR : | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RR : | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RES: | | Tyre : | OK | / | Rim : | / | Hubcap : |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0 | 0 | R | 0 | |
| Rear tyre | 0 | 0 | R | 0 | |

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

| | | |
|-----|---------------------------|--------------------------------|
| [x] | REAR MUDGUARD/LEFT/CENTER | DENT |
| [x] | REAR MUDGUARD/RIGHT/FRONT | DENT |
| [x] | REAR DOOR/LEFT/FRONT | DENT |
| [x] | WINDSCREEN/RIGHT | CHIPS |
| [x] | FRONT DOOR/RIGHT/REAR | SCRATCH (WITHOUT PAINT DAMAGE) |
| [x] | BONNET/CENTER/LEFT/FRONT | CHIPS |
| [x] | FRONT BUMPER/CENTER/LEFT | SCRATCH WITH PAINT DAMAGE |
| [x] | FRONT BUMPER/CENTER/RIGHT | SCRATCH WITH PAINT DAMAGE |

STATUS: NOT ACCEPTABLE

Bodywork \& windows

| [x] | FRONT DOOR/LEFT/CENTER | OTHER DAMAGES | INT. RUBBER | | |
|--------|------------------------|------------------|-------------|-------|-----------|
| Number | Code | Description | Unit price | Depr. | Total |
| 3 | I 1 i-vab-ander-01 | REPAIR (PER 15') | 18.74 EUR | | 18.74 EUR |

Interior

| [x] | BACK SHELF | OTHER DAMAGES | | | |
|-----|----------------|-------------------|---------------|-------|-------|
| | | Repair paint - LI | New paint - E | Depr. | Total |
| 1 | 0 LU =0.00 EUR | 0 EUR | | 50 % | |

Others

| | HUB CAP FR | | | | |
|---|----------------|-------------------|---------------|-------|-------|
| | | Repair paint - LI | New paint - E | Depr. | Total |
| 2 | 0 LU =0.00 EUR | | | 50 % | |

Pieces

| Number | Code | Description | Unit price | Depr. | Total |
|--------|------|-----------------|------------|-------|-----------|
| 1 | 1 | CORD BACK SHELF | 27.00 EUR | 50 % | 27.00 EUR |
| Number | Code | Description | Unit price | Depr. | Total |
| 2 | 1 | WHEEL CAP | 30.00 EUR | 50 % | 30.00 EUR |

| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
|-------|-------|-------|---|---|---|---|---|---|----|
| 27.00 | 30.00 | 18.74 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 13.50 | 15.00 | 18.74 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

| INNOVATIVE | TRADITIONAL | GENERAL | |
|------------|-------------|---------|--------------------|
| 18.74 | 57.00 | 0 | 75.74 |
| HOG: 0 | BG: 0 | | NA Deprec. 47.24 |
| | | | 0.00% |
| | | | TOTAL 47.24 |

[x] = Status Modification


Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

| | | |
|---------------------------------------------|------------------------------------------------|-----------------------------------------------|
| Extra Time : 0 min | Waiting time : 0 min Reason : | Towing time : 0 min Reason : |
| NOT EXECUTED : No Reason : | | |
| Remark : NAVI OK [x] | | |

Prices in EUR without VAT

| | |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------|
| Authorized by customer : Remark authorized customer : Date : 14/11/2017 Hour : 11:47 Company : Executed by VAB Fleet Services E-Mail : @ | Executed by VAB Fleet Services |
| Signature authorized by customer  | |