

D90XAZ

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	165621 KM
File nr. :	1456468	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DOT496 / WF0HXXWPBHCK08594 /		yr of constructionr :	/
E-File nr. :		First registration :	10/07/2012
VFS-nr. :		Color :	BLACK
Make + Model :	FORD / C-MAX	Fuel type :	DIESEL
Object nr. :	51380	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	QUINTIENS NV	Co2:	124g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :	GR.C-MAX Trend St/St 95PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	MONOVOLUME	Engine size:	1560
Gear box :	Manueel	Number of places:	7
Number of gears:	6	Number of doors:	5
HP:	95	kW:	70
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :		Transport licence :		
Tax certificate :		Navigation CD/SD/DVD	OK	[x]
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :	OK	[x]	Oil level :	OK
			Filled up :	0

Wheels and tyres: Winter tires

Wheel FL:	[x]	BRIDGESTONE	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel RL :	[x]	BRIDGESTONE	Tyre :	OK	[x]	4-6/	Rim :	[x]	WHEEL SCRATCHED
Wheel FR :	[x]	BRIDGESTONE	Tyre :	[x]	OK	[x]	4-6/	Rim :	[x]
Wheel RR :	[x]	BRIDGESTONE	Tyre :	OK	[x]	4-6/	Rim :	[x]	WHEEL SCRATCHED
Wheel RES:	[x]		Tyre :	OK	/		Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	215	55	R	16	M+S
Rear tyre	215	55	R	16	M+S

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR DOOR/CENTER/RIGHT	DENT
[x]	REAR DOOR/RIGHT/RIGHT	SCRATCH WITH PAINT DAMAGE
[x]	REAR WINDOW/LEFT	SCRATCH WITH PAINT DAMAGE
[x]	REAR MUDGUARD/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE
[x]	REAR DOOR/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE
[x]	REAR DOOR/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE
[x]	FRONT DOOR/RIGHT/CENTER	DENT
[x]	FRONT/LEFT	SCRATCH WITH PAINT DAMAGE
[x]	ROOF/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE

Interior

[x]	STEERING WHEEL	SCRATCHED
[x]	DOOR IN FL	SCRATCHED

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE				
		Repair paint - LI	New paint - E	Depr.	Total	
5	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR	
[x]	REAR LIGHT/LEFT	HOLE/CRACK/TORN				
		Repair paint - LI	New paint - E	Depr.	Total	
8	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR	
[x]	REAR MUDGUARD/LEFT/CENTER	DENT				
	Number	Code	Description	Unit price	Depr.	Total
4	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR

[x]	WINDSCREEN/CENTER/RIGHT		HOLE/CRACK/TORN		
		Repair paint - LI	New paint - E	Depr.	Total
2	25 LU =120.00 EUR	0 EUR		50 %	120.00 EUR
[x]	FRONT THRESHOLD/RIGHT/CENTER		SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr.	Total
6	10 LU =48.00 EUR	0 EUR		50 %	48.00 EUR
[x]	FRONT MUDGUARD/RIGHT/FRONT		DENT		
		Repair paint - LI	New paint - E	Depr.	Total
3	20 LU =96.00 EUR	0 EUR	237.22 EUR	50 %	333.22 EUR
[x]	FRONT BUMPER/RIGHT/SIDE		SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr.	Total
3	15 LU =72.00 EUR	211.80 EUR		50 %	283.80 EUR

Interior

[x]	BOOT LID IN		OTHER DAMAGES		
		Repair paint - LI	New paint - E	Depr.	Total
1	20 LU =96.00 EUR	0 EUR		50 %	96.00 EUR

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 1	specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR	14.58 EUR

RIM REAR RIGHT

Number	Code	Description	Unit price	Depr.	Total
7	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	BEKLEDING L	90.00 EUR	50 %	90.00 EUR
1	1	BEKLEDING R	90.00 EUR	50 %	90.00 EUR
1	1	KOFFERBEKLEDING	75.00 EUR	50 %	75.00 EUR
1	1	LUGGAGE COVER	240.00 EUR	50 %	240.00 EUR
2	1	WIND SCREEN	367.20 EUR	50 %	367.20 EUR
3	1	BUMPER GRID	30.00 EUR	50 %	30.00 EUR
3	1	SPOILER	50.00 EUR	50 %	50.00 EUR
3	1	FENDER FR	172.80 EUR	50 %	172.80 EUR
6	1	DOORSTEP	45.00 EUR	50 %	45.00 EUR
8	1	REAR LIGHT	90.00 EUR	50 %	90.00 EUR

1	2	3	4	5	6	7	8	9	10
605.58	487.20	869.82	63.00	211.80	93.00	95.00	114.00	0	0
310.08	243.60	434.91	63.00	105.90	46.50	95.00	57.00	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
172.58	2366.82	0	2539.40
HOG: 0	BG: 0		NA Deprec. 1355.99
			0.00%
			TOTAL 1355.99

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 14/11/2017 Hour : 10:40 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	