

EFFECTIVE     NOT EXECUTED     COLLECTION     DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: DIRTY [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	156416 KM
<b>File nr. :</b>	1457018	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1FXG417 / WF0XXXTTFXDC66975 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	26/11/2013
<b>VFS-nr. :</b>		<b>Color :</b>	WHITE
<b>Make + Model :</b>	FORD / TRANSIT	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>	702881	<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	EURO 5
<b>Customer company :</b>	PIRTEK BELGIUM BVBA	<b>Co2:</b>	209g/km
<b>Driver :</b>		<b>Remote controls:</b>	1
<b>Covering :</b>	TISSUE	<b>Number keys :</b>	1 [x]
<b>Vehicle kind :</b>	TRUCK, LORRY	<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>	TRANSIT 350M B/F MWB Amb.DPF(EU5) 125PK	<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>	Yes	<b>Metallic paint:</b>	
<b>Variant car:</b>	BESTELWAGEN	<b>Engine size:</b>	2198
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	3
<b>Number of gears:</b>	5	<b>Number of doors:</b>	4
<b>HP:</b>	125	<b>kW:</b>	92
<b>Fisc HP</b>		<b>Imported vehicle:</b>	No
<b>Animals transported:</b>	No	<b>Smoked in vehicle:</b>	No
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	No
		<b>Use:</b>	Unknown

**General condition:**

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :		Oil level :	OK	[x]
		Filled up :	0	

## Wheels and tyres: Summer tires

Wheel FL:	[x]	UNIROYAL	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	
Wheel RL :	[x]	HANGKOOK	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	[x] MISSING/INCOMPLETE
Wheel FR :	[x]	UNIROYAL	Tyre :	[x]	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel RR :	[x]	HANGKOOK	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	[x] MISSING/INCOMPLETE
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	215	75	R	16	
Rear tyre	215	75	R	16	

Remark :

## Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x] REAR DOOR/CENTER/LEFT DENT

### Interior

[x] SEAT FL OTHER DAMAGES

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	ROOF/REAR/LEFT	SCRATCH WITH PAINT DAMAGE	+DEUK		
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
5	0 LU =0.00 EUR	361.13 EUR		50 %	361.13 EUR

[x]	FRONT BUMPER/LEFT/SIDE	HOLE/CRACK/TORN			
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
4	0 LU =0.00 EUR	0 EUR		50 %	
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
4	20 LU =96.00 EUR	0 EUR		50 %	96.00 EUR

[x]	BONNET/CENTER/LEFT/FRONT	DENT				
	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
3	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
3	I 1	i-vab-uitd-02	BEAT OUT DENT SUPPL	19.80 EUR		19.80 EUR

### Interior

[x]	BOOT LID IN	OTHER DAMAGES			
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
6	0 LU =0.00 EUR	0 EUR		50 %	
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
6	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

### Others

CLEANLINESS INTERIOR

	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
1	I 4	bestelwagen-cabine-a-vab-rein-05	CLEANING INTERIOR	11.47 EUR		45.88 EUR

HUB CAP REAR L

	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR			50 %	

HUB CAP REAR RIGHT

	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR			50 %	

**Pieces**

Number	Code	Description	Unit price	Depr.	Total
2	1	WHEEL CAP	22.50 EUR	50 %	22.50 EUR
2	1	WHEEL CAP	22.50 EUR	50 %	22.50 EUR
4	1	FRONT BUMPER	302.40 EUR	50 %	302.40 EUR
6	1	PANEEL	50.00 EUR	50 %	50.00 EUR

1	2	3	4	5	6	7	8	9	10
45.88	45.00	82.80	398.40	361.13	74.00	0	0	0	0
45.88	22.50	82.80	199.20	180.56	37.00	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
128.68	878.53	0	<b>1007.21</b>
HOG: 0	BG: 3		NA Deprec. 567.94
			0.00%
			<b>TOTAL 567.94</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No		
<b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 16/11/2017 <b>Hour :</b> <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
<b>Signature authorized by customer</b> 	