

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	74699 KM
File nr. :	1456815	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1EAT528 / WDD2462001J108809 /		yr of constructionr :	/
E-File nr. :		First registration :	05/10/2012
VFS-nr. :		Color :	BLACK
Make + Model :	MERCEDES / B	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	EDF LUMINUS	Co2:	113g/km
Driver :		Remote controls:	2
Covering :	IMITATION LEATHER	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :	B 180 CDI BE 109PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1796
Gear box :	Automaat algemeen	Number of places:	5
Number of gears:		Number of doors:	5
HP:	109	kW:	80
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number : OK	Service manual : OK [x]
Cert. of reg. / Part 1:	Cert. of conformity : OK
Cert. of reg. copy / Part 2: OK [x]	Insurance certificate :
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher : OK [x]
First aid kit : OK [x]	Warning triangle : OK [x]
Jack, wheelspanner :	Oil level : OK [x]
	Filled up : 0

Wheels and tyres: Summer tires

Wheel FL: [x] MICHELIN Tyre : OK [x] 4-6/ Rim : / Hubcap : [x] SCRATCHED
Wheel RL : [x] MICHELIN Tyre : OK [x] 4-6/ Rim : / Hubcap : [x] SCRATCHED
Wheel FR : [x] MICHELIN Tyre : [x] OK [x] 4-6/ Rim : / Hubcap : [x] SCRATCHED
Wheel RR : [x] MICHELIN Tyre : OK [x] 4-6/ Rim : / Hubcap : [x] SCRATCHED
Wheel RES: [x] ANDERE Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	195	65	R	15	T
Rear tyre	195	65	R	15	T

Remark : REP. KIT OK

Wheels and tyres:

Wheel FL: Tyre : OK / Rim : / Hubcap :
Wheel RL : Tyre : OK / Rim : / Hubcap :
Wheel FR : Tyre : OK / Rim : / Hubcap :
Wheel RR : Tyre : OK / Rim : / Hubcap :
Wheel RES: Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR MUDGUARD/LEFT/REAR	DENT	
[x]	REAR MUDGUARD/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE	
[x]	REAR MUDGUARD/RIGHT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)	POL.
[x]	REAR MUDGUARD/RIGHT/FRONT	DENT	
[x]	REAR DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE	
[x]	REAR DOOR/LEFT/FRONT	SCRATCH (WITHOUT PAINT DAMAGE)	POL.
[x]	REAR DOOR/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE	
[x]	REAR THRESHOLD/RIGHT/REAR	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	ROOF STYLE/FRONT/RIGHT/CENTER	OTHER DAMAGES	OVBH POL.
[x]	BONNET/CENTER/LEFT	CHIPS	

Interior

[x]	BOOT LID IN	SCRATCHED
-----	-------------	-----------

Accessories and others

[x]	OUTSIDE MIRROR RIGHTHAND SIDE	SCRATCH WITH PAINT DAMAGE
-----	-------------------------------	---------------------------

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/RIGHT/CORNER	DENT
-----	--------------------------	------

	Repair paint - LI	New paint - E	Depr.	Total
4	0 LU =0.00 EUR	211.80 EUR	50 %	211.80 EUR

Number	Code	Description	Unit price	Depr.	Total
4	I 1	i-vab-kunst-01	PLASTICS REPAIR	110.64 EUR	110.64 EUR

[x]	FRONT DOOR/RIGHT/REAR	DENT
-----	-----------------------	------

Number	Code	Description	Unit price	Depr.	Total
5	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR	63.00 EUR

Number	Code	Description	Unit price	Depr.	Total
5	I 1	i-vab-uitd-02	BEAT OUT DENT SUPPL	19.80 EUR	19.80 EUR

[x]	FRONT BUMPER/RIGHT		SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E	Depr.	Total
3	0	LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

Interior

[x]	DASHBORD		SCRATCHED			
	Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-intdash-01	PLASTICS REPAIR INTERIRO	110.64 EUR		110.64 EUR

[x]	SEAT FL		STAIN			
	Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-rein-07	CLEANING (PER 15')	14.58 EUR		14.58 EUR

[x]	FLOOR BOOT		STAIN			
	Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-rein-07	CLEANING (PER 15')	14.58 EUR		14.58 EUR

Others

HUB CAP FL						
			Repair paint - LI	New paint - E	Depr.	Total
2	0	LU =0.00 EUR			50 %	

HUB CAP REAR L						
			Repair paint - LI	New paint - E	Depr.	Total
2	0	LU =0.00 EUR			50 %	

HUB CAP REAR RIGHT						
			Repair paint - LI	New paint - E	Depr.	Total
2	0	LU =0.00 EUR			50 %	

HUB CAP FR						
			Repair paint - LI	New paint - E	Depr.	Total
2	0	LU =0.00 EUR			50 %	

Pieces					
Number	Code	Description	Unit price	Depr.	Total
2	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR
Number	Code	Description	Unit price	Depr.	Total
2	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR
Number	Code	Description	Unit price	Depr.	Total
2	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR
Number	Code	Description	Unit price	Depr.	Total
2	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR
Number	Code	Description	Unit price	Depr.	Total
3	2	CHROOMSTRIP	20.00 EUR	50 %	40.00 EUR

1	2	3	4	5	6	7	8	9	10
139.80	120.00	251.80	322.44	82.80	0	0	0	0	0
139.80	60.00	125.90	216.54	82.80	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
333.24	583.60	0	916.84
HOG: 0	BG: 0		NA Deprec. 625.04
			0.00%
			TOTAL 625.04

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark : NAVI OK [x]		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 15/11/2017 Hour : 11:30 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	