

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: CLEAN [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	107442 KM
<b>File nr. :</b>	1434561	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1FCZ110 / WF0GXXGBBGDP23756 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	28/05/2013
<b>VFS-nr. :</b>		<b>Color :</b>	BLACK
<b>Make + Model :</b>	FORD / MONDEO CLIPPER	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>		<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	EURO 5
<b>Customer company :</b>	BELGACOM INT. CARRIER SERVICES NV	<b>Co2:</b>	112g/km
<b>Driver :</b>		<b>Remote controls:</b>	
<b>Covering :</b>	LEATHER	<b>Number keys :</b>	2 [x]
<b>Vehicle kind :</b>		<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>	MONDEO CLIP Econetic Titanium 115PK	<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>	No	<b>Metallic paint:</b>	Yes
<b>Variant car:</b>	BREAK	<b>Engine size:</b>	1560
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	5
<b>Number of gears:</b>	6	<b>Number of doors:</b>	5
<b>HP:</b>	116	<b>kW:</b>	85
<b>Fisc HP</b>		<b>Imported vehicle:</b>	
<b>Animals transported:</b>		<b>Smoked in vehicle:</b>	
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	
		<b>Use:</b>	Unknown

**General condition:**

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	OK	[x]
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :	OK	[x]	Oil level :	OK
			Filled up :	0

## Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RL :	[x]	BRIDGESTONE	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	[x]	BRIDGESTONE	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :			/	Hubcap :	

  

[x]	Width	Height	Type	Rim	Index
Front tyre	215	55	R	16	V
Rear tyre	215	55	R	16	V

Remark :

## Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

  

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :



## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

- [x] REAR DOOR/LEFT/FRONT DENT
- [x] WINDSCREEN/CENTER/LEFT CHIPS

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT		DENT			
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>	
3	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR	
[x]	REAR MUDGUARD/LEFT/CENTER		DENT			
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>	
2	0 LU =0.00 EUR	308.20 EUR		50 %	308.20 EUR	
[x]	REAR DOOR/RIGHT/REAR		DENT			
	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
4	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
[x]	FRONT DOOR/RIGHT/REAR		DENT			
	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
5	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
5	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR

### Pieces

Number	Code	Description	Unit price	Depr.	Total
3	1	SIERLIJST	75.00 EUR	50 %	75.00 EUR

1	2	3	4	5	6	7	8	9	10
0	308.20	286.80	63.00	126.00	0	0	0	0	0
0	154.10	143.40	63.00	126.00	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
189.00	595.00	0	<b>784.00</b>
HOG: 0	BG: 0		NA Deprec. 486.50
			0.00%
			<b>TOTAL 486.50</b>



[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

UNDER CONDITION - DUSTY VEHICLE

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No		
<b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 16/10/2017 <b>Hour :</b> 14:28 <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
<b>Signature authorized by customer</b>  	