

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	114626
File nr. :	1458006	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FTW140 / JTMVHREV50D010262 /		yr of constructionr :	2013 / 00
E-File nr. :		First registration :	23/10/2013
VFS-nr. :		Color :	WHITE
Make + Model :	TOYOTA / RAV4	Fuel type :	DIESEL
Object nr. :	15195	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	VLERICK BUSINESS SCHOOL	Co2:	127g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :	RAV4 4x2 Lounge 124PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	SUV	Engine size:	1998
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	124	kW:	91
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :		Transport licence :		
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
		Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK
Jack, wheelspanner :	OK	[x]	Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	2-4 /	Rim :	/	Hubcap :
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	4-6 /	Rim :	/	Hubcap :
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	2-4 /	Rim :	/
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	4-6 /	Rim :	/	Hubcap :
Wheel RES:	[x]		Tyre :	OK	/		Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	225	65	R	17	H
Rear tyre	225	65	R	17	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE
[x]	FRONT DOOR/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE
[x]	BONNET/CENTER/LEFT/FRONT	CHIPS

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/RIGHT/CORNER	DENT
-----	--------------------------	------

		Repair paint - LI	New paint - E	Depr.	Total
1	15 LU =72.00 EUR	0 EUR		50 %	72.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	REAR BUMPER	343.20 EUR	50 %	343.20 EUR
Number	Code	Description	Unit price	Depr.	Total
1	1	REAR LIGHT	90.00 EUR	50 %	90.00 EUR

1	2	3	4	5	6	7	8	9	10
505.20	0	0	0	0	0	0	0	0	0
252.60	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	505.20	0	505.20
HOG: 0	BG: 0		NA Deprec. 252.60
			0.00%
			TOTAL 252.60

APPRAISAL

www.vabfleetservices.be

Date : 15/11/2017

4/4

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min	Towing time : 0 min
	Reason :	Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer :	Executed by VAB Fleet Services
Remark authorized customer :	
Date : 15/11/2017 Hour : 13:38	
Company : Executed by VAB Fleet Services E-Mail : @	
Signature authorized by customer 	