

☒ EFFECTIVE
 ☐ NOT EXECUTED
 ☒ COLLECTION
 ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	187898 KM
File nr. :	1458845	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1CDU109 / W0LPD8EA3C8014367 /		yr of constructionr :	/
E-File nr. :		First registration :	27/10/2011
VFS-nr. :		Color :	GREY
Make + Model :	OPEL / ASTRA BREAK	Fuel type :	DIESEL
Object nr. :	11065	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	AQUAFIN NV	Co2:	109g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	ASTRA BRE ecoFLEX Enjoy FAP 95PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1248
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	5
HP:	95	kW:	70
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK
Cert. of reg. copy / Part 2:	OK [x]	Insurance certificate :	
Warning vest :	OK [x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	OK [x]
Mobile phone kit :		Extinguisher :	OK [x]
		Warning triangle :	OK [x]
First aid kit :	OK [x]	Oil level :	OK [x]
Jack, wheelspanner :		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	4-6 /	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel RL :	[x]	PIRELLI	Tyre :	OK	[x]	2-4 /	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	4-6 /	Rim :	/	Hubcap :	[x]	SCRATCHED
Wheel RR :	[x]	PIRELLI	Tyre :	OK	[x]	2-4 /	Rim :	/	Hubcap :			
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :			

[x]	Width	Height	Type	Rim	Index
Front tyre	205	60	R	16	H
Rear tyre	205	60	R	16	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/SIDE/RIGHT/FRONT	OTHER DAMAGES			
		Repair paint - LI	New paint - E	Depr.	Total
2	15 LU =72.00 EUR	0 EUR		50 %	72.00 EUR

Others

HUB CAP FL						
			Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR				50 %	
HUB CAP REAR L						
			Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR				50 %	
HUB CAP FR						
			Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR				50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR
Number	Code	Description	Unit price	Depr.	Total
1	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR
Number	Code	Description	Unit price	Depr.	Total
1	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR

1	2	3	4	5	6	7	8	9	10
90.00	72.00	0	0	0	0	0	0	0	0
45.00	36.00	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	162.00	0	162.00
HOG: 0	BG: 0		NA Deprec. 81.00
			0.00%
			TOTAL 81.00

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 16/11/2017 Hour : Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	