

D8D1G2

☒ EFFECTIVE
 ☐ NOT EXECUTED
 ☒ COLLECTION
 ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	148729 KM
File nr. :	1455415	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1GKI114 / W0LGT8ES0E1035636 /		yr of constructionr :	/
E-File nr. :		First registration :	03/03/2014
VFS-nr. :		Color :	BLACK
Make + Model :	OPEL / INSIGNIA SPORTS TOURER	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :	A	Environment Class:	EURO 5
Customer company :	ILOMAR NV	Co2:	104g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1956
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	140	kW:	103
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown

General condition:	
--------------------	--

Original registr. number :	OK	Service manual :	OK	[x]	
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:			Insurance certificate :		
Warning vest :			Transport licence :		
Tax certificate :			Navigation CD/SD/DVD		
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :			Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	BRIDGESTONE	Tyre :	OK	[x]	2-4 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RL :	[x]	BRIDGESTONE	Tyre :	OK	[x]	2-4 /	Rim :			/	Hubcap :
Wheel FR :	[x]	BRIDGESTONE	Tyre :	[x]	OK	[x]	2-4 /	Rim :		/	Hubcap :
Wheel RR :	[x]	BRIDGESTONE	Tyre :	OK	[x]	2-4 /	Rim :			/	Hubcap :
Wheel RES:	[x]		Tyre :	OK		/	Rim :			/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	225	55	R	17	H
Rear tyre	225	55	R	17	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR MUDGUARD/RIGHT/FRONT SCRATCH WITH PAINT DAMAGE

[x] FRONT BUMPER/CENTER/LEFT SCRATCH WITH PAINT DAMAGE

Interior

[x] ARM REST OTHER DAMAGES

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] REAR BUMPER/LEFT/LEFT SCRATCH WITH PAINT DAMAGE

		Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR	254.16 EUR		50 %	254.16 EUR

[x] REAR DOOR/CENTER/RIGHT DENT

Number	Code	Description	Unit price	Depr.	Total
3	I 1 i-vab-sp-01	SPOTREPAIR	115.56 EUR		115.56 EUR

[x] REAR DOOR/RIGHT/CENTER SCRATCH WITH PAINT DAMAGE

		Repair paint - LI	New paint - E	Depr.	Total
4	0 LU =0.00 EUR	382.02 EUR		50 %	382.02 EUR

[x] FRONT THRESHOLD/LEFT/FRONT DENT

		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	372.60 EUR		50 %	372.60 EUR

[x] WINDSCREEN/CENTER/LEFT WINDOW DAMAGE IN ZICHTVELD

		Repair paint - LI	New paint - E	Depr.	Total
6	25 LU =120.00 EUR	0 EUR		50 %	120.00 EUR

[x] FRONT/LEFT DENT

		Repair paint - LI	New paint - E	Depr.	Total
1	10 LU =48.00 EUR	0 EUR		50 %	48.00 EUR

[x] FRONT BUMPER/RIGHT/SIDE OTHER DAMAGES

Number	Code	Description	Unit price	Depr.	Total
1	I 1 i-vab-ander-01	REPAIR (PER 15')	18.74 EUR		18.74 EUR

Interior

[x] FLOOR FL

CUT / TORN

	Repair paint - LI	New paint - E	Depr.	Total
5 40 LU =192.00 EUR	0 EUR		50 %	192.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	FRONT	34.56 EUR	50 %	34.56 EUR
Number	Code	Description	Unit price	Depr.	Total
5	1	CARPET	72.00 EUR	50 %	72.00 EUR
Number	Code	Description	Unit price	Depr.	Total
6	1	WIND SCREEN	440.64 EUR	50 %	440.64 EUR

1	2	3	4	5	6	7	8	9	10
101.30	372.60	369.72	382.02	264.00	560.64	0	0	0	0
60.02	186.30	242.64	191.01	132.00	280.32	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
134.30	1915.98	0	2050.28
HOG: 0	BG: 2		NA Deprec. 1092.29
			0.00%
			TOTAL 1092.29

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 09/11/2017 Hour : 10:26 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	