

DDTAIQ

☒ EFFECTIVE    ☐ NOT EXECUTED    ☒ COLLECTION    ☐ DELIVERY

[x] = Status Modification

|                               |                                     |                          |                               |
|-------------------------------|-------------------------------------|--------------------------|-------------------------------|
| Commissionar :                | KBC REMARKETING                     | Cleanliness :            | INT: CLEAN [x] EXT: CLEAN [x] |
| Owner :                       |                                     | Mileage :                | 119431 KM                     |
| File nr. :                    | 1459796                             | Mileage start / arrival: | 0 / 0                         |
| Reg number / Chassis / Ref :  |                                     | Mileag ref. service :    | 0                             |
| 1EWE869 / VF15RJL0H48730212 / |                                     | yr of constructionr :    | /                             |
| E-File nr. :                  |                                     | First registration :     | 05/04/2013                    |
| VFS-nr. :                     |                                     | Color :                  | SILVER                        |
| Make + Model :                | RENAULT / CLIO                      | Fuel type :              | DIESEL                        |
| Object nr. :                  | 49284                               | Fuel :                   |                               |
| Classification :              |                                     | Environment Class:       | EURO 5                        |
| Customer company :            | RANDSTAD GROUP BELGIUM NV           | Co2:                     | 83g/km                        |
| Driver :                      |                                     | Remote controls:         | 2                             |
| Covering :                    | TISSUE                              | Number keys :            | 2 [x]                         |
| Vehicle kind :                | VEHICLE                             | Seats (minivan) :        | 0                             |
| Vehicle type :                | CLIO IV BER e-Expression St&St 90PK | Country registration :   | BELGIUM                       |

|                              |         |                     |         |
|------------------------------|---------|---------------------|---------|
| VAT over the margin - car:   | No      | Metallic paint:     | Yes     |
| Variant car:                 |         | Engine size:        | 1461    |
| Gear box :                   | Manueel | Number of places:   | 5       |
| Number of gears:             | 5       | Number of doors:    | 5       |
| HP:                          | 90      | kW:                 | 66      |
| Fisc HP                      |         | Imported vehicle:   |         |
| Animals transported:         | No      | Smoked in vehicle:  | No      |
| Due date vehicle inspection: |         | Extra set of tires: |         |
|                              |         | Use:                | Unknown |
| General condition:           |         |                     |         |

|                                     |                           |
|-------------------------------------|---------------------------|
| Original registr. number : OK       | Service manual :          |
| Cert. of reg. / Part 1:             | Cert. of conformity : NOK |
| Cert. of reg. copy / Part 2: OK [x] | Insurance certificate :   |
| Warning vest :                      | Transport licence :       |
| Tax certificate :                   | Navigation CD/SD/DVD      |
| Fuel card :                         | Car radio : OK [x]        |
| Mobile phone kit :                  | Extinguisher : OK [x]     |
|                                     | Warning triangle : OK [x] |
| First aid kit : OK [x]              | Oil level : OK [x]        |
| Jack, wheelspanner :                | Filled up : 0             |

## Wheels and tyres: Summer tires

|            |     |             |        |     |     |       |           |       |                          |
|------------|-----|-------------|--------|-----|-----|-------|-----------|-------|--------------------------|
| Wheel FL:  | [x] | BRIDGESTONE | Tyre : | OK  | [x] | 2-4 / | Rim :     | /     | Hubcap :                 |
| Wheel RL : | [x] | BRIDGESTONE | Tyre : | OK  | [x] | 2-4 / | Rim :     | /     | Hubcap :                 |
| Wheel FR : | [x] | BRIDGESTONE | Tyre : | [x] | OK  | [x]   | 2-4 /     | Rim : | / Hubcap : [x] SCRATCHED |
| Wheel RR : | [x] | BRIDGESTONE | Tyre : | OK  | [x] | 2-4 / | Rim : [x] | /     | Hubcap : [x] SCRATCHED   |
| Wheel RES: | [x] |             | Tyre : | OK  |     | /     | Rim :     | /     | Hubcap :                 |

| [x]        | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 185   | 65     | R    | 15  | H     |
| Rear tyre  | 185   | 65     | R    | 15  | H     |

Remark :

## Wheels and tyres:

|            |  |        |    |   |       |   |          |
|------------|--|--------|----|---|-------|---|----------|
| Wheel FL:  |  | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RL : |  | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel FR : |  | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RR : |  | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RES: |  | Tyre : | OK | / | Rim : | / | Hubcap : |

| [x]        | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0     | 0      | R    | 0   |       |
| Rear tyre  | 0     | 0      | R    | 0   |       |

Remark :

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

| [x]    | REAR MUDGUARD/RIGHT/CENTER |             | OTHER DAMAGES | SLECHT HERSTELD |       |  |
|--------|----------------------------|-------------|---------------|-----------------|-------|--|
| Number | Code                       | Description | Unit price    | Depr.           | Total |  |
| 0      | 0                          |             |               |                 |       |  |

| [x]    | FRONT BUMPER/RIGHT/SIDE |                | OTHER DAMAGES    |           |           |  |
|--------|-------------------------|----------------|------------------|-----------|-----------|--|
| Number | Code                    | Description    | Unit price       | Depr.     | Total     |  |
| 2      | I 4                     | i-vab-ander-01 | REPAIR (PER 15') | 18.74 EUR | 74.96 EUR |  |

### Others

|                    |   |                   |               |       |       |  |
|--------------------|---|-------------------|---------------|-------|-------|--|
| HUB CAP REAR RIGHT |   |                   |               |       |       |  |
|                    |   | Repair paint - LI | New paint - E | Depr. | Total |  |
| 1                  | 0 | LU =0.00 EUR      |               | 50 %  |       |  |

|            |   |                   |               |       |       |  |
|------------|---|-------------------|---------------|-------|-------|--|
| HUB CAP FR |   |                   |               |       |       |  |
|            |   | Repair paint - LI | New paint - E | Depr. | Total |  |
| 1          | 0 | LU =0.00 EUR      |               | 50 %  |       |  |

### Pieces

| Number | Code | Description | Unit price | Depr. | Total     |  |
|--------|------|-------------|------------|-------|-----------|--|
| 1      | 1    | WHEEL CAP   | 24.00 EUR  | 50 %  | 24.00 EUR |  |
| Number | Code | Description | Unit price | Depr. | Total     |  |
| 1      | 1    | WHEEL CAP   | 24.00 EUR  | 50 %  | 24.00 EUR |  |

| 1     | 2     | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
|-------|-------|---|---|---|---|---|---|---|----|
| 48.00 | 74.96 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0  |
| 24.00 | 74.96 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0  |

| INNOVATIVE | TRADITIONAL | GENERAL |            |       |  |
|------------|-------------|---------|------------|-------|--|
| 74.96      | 48.00       | 0       | 122.96     |       |  |
| HOG: 0     | BG: 1       |         | NA Deprec. | 98.96 |  |
|            |             |         | 0.00%      |       |  |
|            |             |         | TOTAL      | 98.96 |  |

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

|                               |                                  |                                 |
|-------------------------------|----------------------------------|---------------------------------|
| Extra Time : 0 min            | Waiting time : 0 min<br>Reason : | Towing time : 0 min<br>Reason : |
| NOT EXECUTED : No<br>Reason : |                                  |                                 |
| Remark :                      |                                  |                                 |

## Prices in EUR without VAT

|                                                                                                                                                                      |                                |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------|
| Authorized by customer :<br><br>Remark authorized customer :<br><br>Date : 15/11/2017      Hour : 15:35<br>Company :<br>Executed by VAB Fleet Services<br>E-Mail : @ | Executed by VAB Fleet Services |
| Signature authorized by customer<br><br>                                          |                                |