

D5KO50

☒ EFFECTIVE
 ☐ NOT EXECUTED
 ☒ COLLECTION
 ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	132101 KM
File nr. :	1453186	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1EFB176 / VF1JZ14B647960306 /		yr of constructionr :	2012 / 11
E-File nr. :		First registration :	13/11/2012
VFS-nr. :		Color :	BLUE
Make + Model :	RENAULT / GRAND SCENIC	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	KBC GROEP NV	Co2:	105g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	7 [x]
Vehicle type :	GR.SCENIC Energ.Business 7pl.FAP 110PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	MONOVOLUME	Engine size:	1461
Gear box :	Manueel	Number of places:	7
Number of gears:	6	Number of doors:	5
HP:	110	kW:	81
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :		
Cert. of reg. copy / Part 2:			Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD		
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]	Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL :	[x]	MICHELIN	Tyre :	OK	[x] 2-4 /	Rim :	/	Hubcap :	
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x] 2-4 /	Rim :	/	Hubcap :	
Wheel FR :	[x]	MICHELIN	Tyre :	[x] OK	[x] 2-4 /	Rim :	/	Hubcap :	[x] SCRATCHED
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x] 2-4 /	Rim :	/	Hubcap :	[x] SCRATCHED
Wheel RES:	[x]	ANDERE	Tyre :	OK	/	Rim :	/	Hubcap :	

	[x]	Width	Height	Type	Rim	Index
Front tyre		205	50	R	16	H
Rear tyre		205	50	R	16	H

Remark :

Wheels and tyres:

Wheel FL:	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:	Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR DOOR/RIGHT/FRONT SCRATCH WITH PAINT DAMAGE

[x] BONNET/CENTER/RIGHT/FRONT CHIPS

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] REAR BUMPER/CENTER/RIGHT SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

[x] REAR MUDGUARD/RIGHT/FRONT SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
3 0 LU =0.00 EUR	308.20 EUR		50 %	308.20 EUR

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 4	specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR	58.32 EUR

HUB CAP REAR RIGHT

	Repair paint - LI	New paint - E	Depr.	Total
4 0 LU =0.00 EUR			50 %	

HUB CAP FR

	Repair paint - LI	New paint - E	Depr.	Total
4 0 LU =0.00 EUR			50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
4	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR

Number	Code	Description	Unit price	Depr.	Total
4	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR

1	2	3	4	5	6	7	8	9	10
58.32	211.80	308.20	60.00	0	0	0	0	0	0
58.32	105.90	154.10	30.00	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
58.32	580.00	0	638.32
HOG: 0	BG: 0		NA Deprec. 348.32
			0.00%
			TOTAL 348.32

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 14/11/2017 Hour : 09:28 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	