

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: CLEAN [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	165244 KM
<b>File nr. :</b>	1447644	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
LS4407 / WVGZZZ7PZED038120 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	01/01/1918
<b>VFS-nr. :</b>		<b>Color :</b>	BLACK
<b>Make + Model :</b>	VOLKSWAGEN / TOUAREG	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>	ONBEKEND	<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	
<b>Customer company :</b>	ONBEKEND	<b>Co2:</b>	g/km
<b>Driver :</b>		<b>Remote controls:</b>	2
<b>Covering :</b>	LEATHER	<b>Number keys :</b>	2 [x]
<b>Vehicle kind :</b>	VEHICLE	<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>		<b>Country registration :</b>	LUXEMBOURG

<b>VAT over the margin - car:</b>		<b>Metallic paint:</b>	Yes
<b>Variant car:</b>	SUV	<b>Engine size:</b>	
<b>Gear box :</b>	Automaat algemeen	<b>Number of places:</b>	5
<b>Number of gears:</b>		<b>Number of doors:</b>	5
<b>HP:</b>		<b>kW:</b>	
<b>Fisc HP</b>		<b>Imported vehicle:</b>	No
<b>Animals transported:</b>	No	<b>Smoked in vehicle:</b>	No
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	No
		<b>Use:</b>	Unknown
<b>General condition:</b>			

Original registr. number :		Service manual :	OK
Cert. of reg. / Part 1:	[x]	Cert. of conformity :	
Cert. of reg. copy / Part 2:	[x]	Insurance certificate :	
Warning vest :	OK [x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	OK [x]
Fuel card :		Car radio :	OK
Mobile phone kit :		Extinguisher :	OK
First aid kit :	OK	Warning triangle :	OK
Jack, wheelspanner :		Oil level :	OK
		Filled up :	0

## Wheels and tyres: Summer tires

Wheel FL:	[x]	BRIDGESTONE	Tyre :	OK	2-4/	Rim :	[x]	/	Hubcap :
Wheel RL :	[x]	BRIDGESTONE	Tyre :	OK	2-4/	Rim :		/	Hubcap :
Wheel FR :	[x]	BRIDGESTONE	Tyre :	OK	2-4/	Rim :	[x]	/	Hubcap :
Wheel RR :	[x]	BRIDGESTONE	Tyre :	OK	2-4/	Rim :	[x]	/	Hubcap :
Wheel RES:	[x]		Tyre :	OK	/	Rim :		/	Hubcap :

  

[x]	Width	Height	Type	Rim	Index
Front tyre	255	55	R	18	W
Rear tyre	255	55	R	18	W

Remark :

## Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

  

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x]	ROOF/CENTER/RIGHT	SCRATCH (WITHOUT PAINT DAMAGE)	POLIEREN
[x]	WINDSCREEN/LEFT	CHIPS	
[x]	BONNET/CENTER/LEFT/FRONT	OTHER DAMAGES	TE POLIEREN
[x]	BONNET/CENTER/RIGHT/FRONT	CHIPS	

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	REAR WINDOW/LEFT	SCRATCH WITH PAINT DAMAGE			
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
3	0 LU =0.00 EUR	0 EUR		50 %	
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
3	25 LU =120.00 EUR	0 EUR		50 %	120.00 EUR
[x]	BONNET/CENTER/RIGHT	OTHER DAMAGES	CHEM. INWERKING		
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
1	0 LU =0.00 EUR	348.09 EUR		50 %	348.09 EUR
[x]	LIGHTS/LEFT/FRONT	HOLE/CRACK/TORN	DAGLICHT		
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
2	0 LU =0.00 EUR	0 EUR		50 %	
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
2	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

### Pieces

Number	Code	Description	Unit price	Depr.	Total
2	1	DAGLICHT	50.00 EUR	50 %	50.00 EUR
Number	Code	Description	Unit price	Depr.	Total
3	1	BACK WINDOW	300.00 EUR	50 %	300.00 EUR

1	2	3	4	5	6	7	8	9	10
348.09	74.00	420.00	0	0	0	0	0	0	0
174.04	37.00	210.00	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	842.09	0	<b>842.09</b>
HOG: 0	BG: 2		NA Deprec. 421.04
			0.00%
			<b>TOTAL 421.04</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No <b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 17/10/2017 <b>Hour :</b> 07:57 <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
<b>Signature authorized by customer</b>  	