

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	117375 KM
File nr. :	1457624	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1HVS864 / W0LGT8ER7E1179441 /		yr of constructionr :	2014 / 00
E-File nr. :		First registration :	15/10/2014
VFS-nr. :		Color :	BLACK
Make + Model :	OPEL / INSIGNIA BREAK	Fuel type :	DIESEL
Object nr. :	45231	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	ONBEKEND	Co2:	104g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1956
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	120	kW:	88
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :		Transport licence :		
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :	OK	[x]	Oil level :	OK
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	BRIDGESTONE	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel RL :	[x]	UNIROYAL	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel FR :	[x]	BRIDGESTONE	Tyre :	[x]	OK	[x]	4-6/	Rim :	/
Wheel RR :	[x]	UNIROYAL	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RES:	[x]		Tyre :	OK	/		Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	225	55	R	17	W
Rear tyre	225	55	R	17	W

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] FRONT/RIGHT CHIPS
- [x] ROOF/CENTER/LEFT DENT

STATUS: NOT ACCEPTABLE

Interior

- [x] FLOOR BOOT HOLE

Number	Code	Description	Unit price	Depr.	Total
1	I 1 i-vab-inttap-01	CARPET REPAIR (MAX 3CM LENGTH OR DIAMETER)	43.92 EUR		43.92 EUR
Number	Code	Description	Unit price	Depr.	Total
1	I 1 i-vab-inttap-02	SUPPL REPAIR CARPET	18.00 EUR		18.00 EUR

1	2	3	4	5	6	7	8	9	10
61.92	0	0	0	0	0	0	0	0	0
61.92	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
61.92	0	0	61.92
HOG: 0	BG: 0		NA Deprec. 61.92
			0.00%
			TOTAL 61.92

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 15/11/2017 Hour : 10:24 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	