

EFFECTIVE     NOT EXECUTED     COLLECTION     DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: DIRTY [x] EXT: DIRTY [x]
<b>Owner :</b>		<b>Mileage :</b>	228294 KM
<b>File nr. :</b>	1457101	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1DPX512 / WVVZZZ3CZDE021334 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	01/01/1918
<b>VFS-nr. :</b>		<b>Color :</b>	BLACK
<b>Make + Model :</b>	VOLKSWAGEN / PASSAT BREAK	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>	ONBEKEND	<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	
<b>Customer company :</b>	ONBEKEND	<b>Co2:</b>	g/km
<b>Driver :</b>		<b>Remote controls:</b>	2
<b>Covering :</b>	TISSUE	<b>Number keys :</b>	2 [x]
<b>Vehicle kind :</b>	VEHICLE	<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>		<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>		<b>Metallic paint:</b>	Yes
<b>Variant car:</b>	BREAK	<b>Engine size:</b>	
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	5
<b>Number of gears:</b>	6	<b>Number of doors:</b>	5
<b>HP:</b>		<b>kW:</b>	
<b>Fisc HP</b>		<b>Imported vehicle:</b>	No
<b>Animals transported:</b>	No	<b>Smoked in vehicle:</b>	No
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	No
		<b>Use:</b>	Unknown
<b>General condition:</b>			

<b>Original registr. number :</b>		<b>Service manual :</b>	
<b>Cert. of reg. / Part 1:</b>	NOK [x]	<b>Cert. of conformity :</b>	NOK
<b>Cert. of reg. copy / Part 2:</b>	NOK [x]	<b>Insurance certificate :</b>	
<b>Warning vest :</b>	OK [x]	<b>Transport licence :</b>	
<b>Tax certificate :</b>		<b>Navigation CD/SD/DVD</b>	OK [x]
<b>Fuel card :</b>		<b>Car radio :</b>	OK [x]
<b>Mobile phone kit :</b>		<b>Extinguisher :</b>	OK [x]
<b>First aid kit :</b>	OK [x]	<b>Warning triangle :</b>	OK [x]
<b>Jack, wheelspanner :</b>		<b>Oil level :</b>	OK [x]
		<b>Filled up :</b>	0

## Wheels and tyres: Summer tires

<b>Wheel FL:</b>	[x]	CONTINENTAL	<b>Tyre :</b>	OK [x]	4-6/	<b>Rim :</b>	/	<b>Hubcap :</b>	
<b>Wheel RL :</b>	[x]	DUNLOP	<b>Tyre :</b>	OK [x]	4-6/	<b>Rim :</b>	/	<b>Hubcap :</b>	
<b>Wheel FR :</b>	[x]	CONTINENTAL	<b>Tyre :</b>	[x] OK [x]	4-6/	<b>Rim :</b>	/	<b>Hubcap :</b>	
<b>Wheel RR :</b>	[x]	DUNLOP	<b>Tyre :</b>	OK [x]	4-6/	<b>Rim :</b>	/	<b>Hubcap :</b>	
<b>Wheel RES:</b>	[x]		<b>Tyre :</b>	OK	/	<b>Rim :</b>	/	<b>Hubcap :</b>	

  

[x]	Width	Height	Type	Rim	Index
Front tyre	215	55	R	16	V
Rear tyre	215	55	R	16	V

**Remark :**

## Wheels and tyres:

<b>Wheel FL:</b>		<b>Tyre :</b>	OK	/	<b>Rim :</b>	/	<b>Hubcap :</b>	
<b>Wheel RL :</b>		<b>Tyre :</b>	OK	/	<b>Rim :</b>	/	<b>Hubcap :</b>	
<b>Wheel FR :</b>		<b>Tyre :</b>	OK	/	<b>Rim :</b>	/	<b>Hubcap :</b>	
<b>Wheel RR :</b>		<b>Tyre :</b>	OK	/	<b>Rim :</b>	/	<b>Hubcap :</b>	
<b>Wheel RES:</b>		<b>Tyre :</b>	OK	/	<b>Rim :</b>	/	<b>Hubcap :</b>	

  

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

**Remark :**

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	ROOF STYLE/FRONT/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE	ROESTVORMING		
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	220.18 EUR		50 %	220.18 EUR

### Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 4	specifiek-per-kwartier-a-vab-rein-03 CLEANING INTERIOR	14.58 EUR		58.32 EUR

1	2	3	4	5	6	7	8	9	10
58.32	220.18	0	0	0	0	0	0	0	0
58.32	110.09	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
58.32	220.18	0	<b>278.50</b>
HOG: 0	BG: 0		NA Deprec. 168.41
			0.00%
			<b>TOTAL 168.41</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No <b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 10/11/2017 <b>Hour :</b> <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
<b>Signature authorized by customer</b> 	