

www.vabfleetservices.be Date: 15/11/2017 1/4

DBP42W

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

Cleanliness: Commissionar: **KBC REMARKETING** INT: CLEAN [x] EXT: CLEAN [x] Owner: Mileage : 133281 KM File nr. : Mileage start / arrival: 0 / 01458077 Reg number / Chassis / Ref: Mileag ref. service : 0 yr of constructionr: 1DPK666 / W0LGM8EJ0C1136743 / E-File nr. : First registration: 13/07/2012 Color: VFS-nr.: **PURPLE** Make + Model : Fuel type : OPEL / INSIGNIA BREAK **DIESEL** Object nr. : Fuel: 34314 Classification: **Environment Class:** EURO 5 Customer company: Co2: **BARCO NV** 119g/km Driver : Remote controls: 2 TISSUE Covering: Number keys: 2[x]Vehicle kind: VEHICLE Seats (minivan): 0 INSIGNIA BRE ecoFL.Edit.150Ys DPF 110PK Vehicle type: Country registration: **BELGIUM**

VAT over the margin - car:	No	Metallic paint:	Yes					
Variant car:	BREAK	Engine size:	1956					
Gear box :	Manueel	Number of places:	5					
Number of gears:	6	Number of doors:	5					
нр:	110	kW:	81					
Fisc HP		Imported vehicle:	No					
Animals transported:	No	Smoked in vehicle:	No					
Due date vehicle inspection:		Extra set of tires:	No					
		Use:	Unknown					
General condition:	General condition:							



15/11/2017 Date: www.vabfleetservices.be 2/4

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:			Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD	OK	[x]
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :			Filled up :	0	

Wheels and tyres: Summer tires

Fr	ont tyre		2	45				45			R		18	W	
		[x]	W	idth			Не	eight			Type		Rim	Index	
Wheel RES	: [x]			Tyre:		OK		/	Rim:				/ Hubcap :		
W I DEG				TD.		OW		,	D.				- / TT 1		
Wheel RR:	[x]	CON	TINENTAL	Tyre:		OK	[x]	2-4 /	Rim:				Hubcap:		
Wheel FR:	[x]	MIC	HELIN	Tyre:	[x]	OK	[x]	1.6-2 /	Rim:				Hubcap:		
Wheel RL:	[x]	CON	TINENTAL	Tyre:		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED	•	Hubcap:		
Wheel FL:	[x]	MIC	HELIN	Tyre:		OK	[x]	1.6-2 /	Rim:	[x]	WHEEL SCRATCHED)	Hubcap:		

[x]	Width	Height	Type	Rim	Index
Front tyre	245	45	R	18	W
Rear tyre	245	45	R	18	W

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

 [x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 15/11/2017 3/4

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] FRONT MUDGUARD/LEFT/CENTER SCRATCH WITH PAINT DAMAGE

[x] FRONT BUMPER/RIGHT SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Boo	odywork \& windows										
[x]	[x] REAR DOOR/LEFT/FRONT		SCRATCH WITH PAINT DAMAGE	+DEUK							
		Repair paint - LI	New paint - E	Depr.	Total						
	2 0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR						

Others

RIM FRONT LEFT

	Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM REAR LEFT

Number		Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

1	2	3	4	5	6	7	8	9	10
190.00	318.35	0	0	0	0	0	0	0	0
190.00	159.18	0	0	0	0	0	0	0	0

		GENERAL	TRADITIONAL	INNOVATIVE
508.35		0	318.35	190.00
349.18	NA Deprec.		BG: 0	HOG: 0
	0.00%			
349.18	TOTAL			



www.vabfleetservices.be Date: 15/11/2017 4/4

[x] = Status Modification

Pictures: No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time :	0 min	Waiting time: 0 min		Towing time :	0 min
		Reason:		Reason :	
NOT EXECUTED:	No	<u>'</u>		<u> </u>	
Reason :					
Remark :	-				
Prices in EUR with	nout VAT				
Authorized by customer :			Executed by VAB Fleet Se	rvices	
customer .					
Remark authorized cus	tomer :				
Date :	15/11/2017	Hour:			
Company:					
Executed by VAB Fleet Services					
E-Mail :	@				
Signature authorized by o	customer				
×			 		