

www.vabfleetservices.be Date: 13/11/2017 1/4

DBN9CI

[X] EFFECTIVE [] NOT EXECUTED [] COLLECTION [] DELIVERY

[x] = Status Modification

General condition:

Commissionar:	KBC REMARKETING	Cleaniness:	INT: CLEAN [X] EXT: CLEAN [X]
Owner:		Mileage :	122435 KM
File nr. :	1458025	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0

1EEF484 / YV1FW84A1D1108704 / yr of constructionr: /

E-File nr.: First registration: 06/11/2012

VFS-nr.: Color: GREY

Make + Model: VOLVO / V60 Fuel type: DIESEL

Object nr.: Fuel:

Classification: Environment Class: EURO 5

Customer company: KBC BANK NV Co2: 119g/km

Driver: Remote controls: 2
Covering: TISSUE Number keys: $2 \lceil x \rceil$

Vehicle kind: VEHICLE Seats (minivan): ()

 Vehicle type :
 V60 D2 Kinetic St/St 115PK
 Country registration :
 BELGIUM

Metallic paint: VAT over the margin - car: No Yes **BREAK** 1560 Variant car: Engine size: Gear box: Number of places: 5 Manueel Number of gears: 6 Number of doors: 5 HP: kW: 114 84 Fisc HP Imported vehicle: No Animals transported: No Smoked in vehicle: No Due date vehicle inspection: Extra set of tires: No Use: Unknown



13/11/2017 Date: www.vabfleetservices.be 2/4

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:			Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD	OK	[x]
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :			Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	FIREST	ONE Ty	re:	OK	[x]	>6 /	Rim:			/	Hubcap :		
Wheel RL:	[x]	FIREST	ONE Ty	re:	OK	[x]	>6/	Rim:			/	Hubcap:		
Wheel FR:	[x]	FIREST	ONE Ty	re: [x] OK	[x]	>6/	Rim:	[x]	WHEEL SCRATCHED	,	Hubcap:		
Wheel RR:	[x]	FIREST	ONE Ty	re:	OK	[x]	>6 /	Rim:			/	Hubcap:		
Wheel RES:	[x]		Ty	re:	OK		/	Rim:			/	Hubcap:		
														_
		[x]	Width			H	leight			Type		Rim	Index]
Fron	nt tyre		205				60			R		16	Н	1

Front tyre 205 60 R 16	Н
Rear tyre 205 60 R 16	Н

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:
i					

_	[x]	Width	Height	Туре	Rim	Index
	Front tyre	0	0	R	0	
	Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 13/11/2017 3/4

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR DOOR/LEFT/REAR

[x] BONNET/CENTER/LEFT SCRATCH (WITHOUT PAINT DAMAGE) POLIEREN

STATUS: NOT ACCEPTABLE

Bodywork \& windows

REAR BUMPER/CENTER/RIGHT		SCRATCH WITH PAINT DAMAGE	+DEUK	
	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

DENT

[x] FRONT BUMPER/RIGHT SCRATCH WITH PAINT DAMAGE

 Repair paint - LI
 New paint - E
 Depr.
 Total

 1 0 LU = 0.00 EUR
 211.80 EUR
 50 %
 211.80 EUR

[x] FRONT BUMPER/RIGHT/SIDE SCRATCH WITH PAINT DAMAGE

Number Code Description Unit price Depr. Total

0 0

[x]

1	2	3	4	5	6	7	8	9	10
211.80	211.80	0	0	0	0	0	0	0	0
105.90	105.90	0	0	0	0	0	0	0	0

		GENERAL	TRADITIONAL	INNOVATIVE
423.60		0	423.60	0
211.80	NA Deprec.		BG: 0	HOG: 0
	0.00%			
211.80	TOTAL			



www.vabfleetservices.be Date: 13/11/2017 4/4

[x] = Status Modification

Pictures: No

CIRCUMSTANCES

UNDER CONDITION - VEHICLE WET

Extra Time :	0 min	Waiting time :	0 min	Towing time :	0 min
		Reason:		Reason:	
NOT EXECUTED:	No	<u> </u>			
Reason:					
Remark :					
Prices in EUR wit	hout VAT				
A-a			English day WAD Floor	G	
Authorized by customer :			Executed by VAB Fleet	Services	
Remark authorized cu	stomer:				
Deter	12/11/2017	TT			
Date :	13/11/2017	Hour :			
Company:					
Executed by VAB Flee Services	t				
E-Mail:	@				
Signature authorized by	customer				
×					