

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	39282 KM
File nr. :	1447581	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
HL8965 / WBAXX110100R37001 /		yr of constructionr :	/
E-File nr. :		First registration :	26/10/2015
VFS-nr. :		Color :	BLACK
Make + Model :	BMW / X4	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	
Customer company :	PWC	Co2:	g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	XDRIVE 20D	Country registration :	LUXEMBOURG

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	SUV	Engine size:	1995
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	190	kW:	140
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number : OK	Service manual :
Cert. of reg. / Part 1: OK [x]	Cert. of conformity : NOK [x] MISSING/INCOMPLETE
Cert. of reg. copy / Part 2: NOK	Insurance certificate :
Warning vest : OK [x]	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher : OK [x]
First aid kit : OK [x]	Warning triangle : OK [x]
Jack, wheelspanner : [x]	Oil level : OK [x]
	Filled up : 0

Wheels and tyres: Winter tires

Wheel FL: [x] PIRELLI	Tyre : OK [x] 4-6/	Rim : /	Hubcap :
Wheel RL : [x] PIRELLI	Tyre : OK /	Rim : /	Hubcap :
Wheel FR : [x] PIRELLI	Tyre : [x] OK [x] 4-6/	Rim : /	Hubcap :
Wheel RR : [x] PIRELLI	Tyre : OK /	Rim : /	Hubcap :
Wheel RES: [x]	Tyre : OK /	Rim : /	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	225	60	R	17	WINTER H
Rear tyre	225	60	R	17	WINTER H

Remark :

Wheels and tyres:

Wheel FL:	Tyre : OK /	Rim : /	Hubcap :
Wheel RL :	Tyre : OK /	Rim : /	Hubcap :
Wheel FR :	Tyre : OK /	Rim : /	Hubcap :
Wheel RR :	Tyre : OK /	Rim : /	Hubcap :
Wheel RES:	Tyre : OK /	Rim : /	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR MUDGUARD/RIGHT/CENTER	DENT	
[x]	REAR DOOR/RIGHT/FRONT	DENT	2X
[x]	BONNET/CENTER/RIGHT	OTHER DAMAGES	ISOLATION RONGEE

Interior

[x]	BOOT LID IN	SCRATCHED
-----	-------------	-----------

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR MUDGUARD/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE	ELARGISSEUR
		Repair paint - LI	New paint - E
		Depr.	Total
1	0 LU =0.00 EUR	0 EUR	50 %

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	SIDE PROTECTION	17.28 EUR	50 %	17.28 EUR

1	2	3	4	5	6	7	8	9	10
17.28	0	0	0	0	0	0	0	0	0
8.64	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	17.28	0	17.28
HOG: 0	BG: 2		NA Deprec. 8.64
			0.00%
			TOTAL 8.64

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark : 3 CLES 1 INCOMPLETE [x]		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 06/11/2017 Hour : 11:36 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	