

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	173442 KM
File nr. :	1442110	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DRY285 / WVVZZZ1KZDM601440 /		yr of constructionr :	/
E-File nr. :		First registration :	01/01/1918
VFS-nr. :		Color :	GREY
Make + Model :	VOLKSWAGEN / GOLF	Fuel type :	DIESEL
Object nr. :	60563	Fuel :	
Classification :	E	Environment Class:	
Customer company :	GREENYARD FRESH BELGIUM NV	Co2:	g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	
Variant car:	BREAK	Engine size:	
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	5
HP:		kW:	
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown

General condition:

Original registr. number :	NOK	Service manual :	OK
Cert. of reg. / Part 1:	NOK [x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :	
Warning vest :	OK	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	OK
Fuel card :		Car radio :	OK
Mobile phone kit :		Extinguisher :	OK
First aid kit :	OK	Warning triangle :	
Jack, wheelspanner :	OK	Oil level :	OK
		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	CONTINENTAL	Tyre :	OK	2-4/	Rim :	WHEEL SCRATCHED	/	Hubcap :
Wheel RL :	CONTINENTAL	Tyre :	OK	4-6/	Rim :		/	Hubcap :
Wheel FR :	CONTINENTAL	Tyre :	OK	2-4/	Rim :	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	CONTINENTAL	Tyre :	OK	4-6/	Rim :	WHEEL SCRATCHED	/	Hubcap :
Wheel RES:	CONTINENTAL	Tyre :	OK	>6/	Rim :		/	Hubcap :

	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	H
Rear tyre	205	55	R	16	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

Conclusion

Bodywork \& windows

[x] BONNET/CENTER/LEFT/FRONT CHIPS

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR MUDGUARD/RIGHT/FRONT DENT

[x] REAR DOOR/LEFT/FRONT DENT

[x] REAR DOOR/RIGHT/REAR DENT

[x] FRONT DOOR/RIGHT/FRONT DENT X2

[x] FRONT BUMPER/CENTER/LEFT CHIPS

Interior

[x] BOOT LID IN CARVED

Accessories and others

[x] OUTSIDE MIRROR RIGHTHAND SIDE SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] REAR DOOR/RIGHT/FRONT DENT

Number	Code	Description	Unit price	Depr.	Total
2	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 3 personenwagen-a-vab-rein-02	CLEANING INTERIOR	11.47 EUR		34.41 EUR

RIM FRONT LEFT

Number	Code	Description	Unit price	Depr.	Total
3	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
3	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

1	2	3	4	5	6	7	8	9	10
34.41	63.00	190.00	0	0	0	0	0	0	0
34.41	63.00	190.00	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
287.41	0	0	287.41
HOG: 0	BG: 0		NA Deprec. 287.41
			0.00%
			TOTAL 287.41

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark : NAVI OK		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 28/09/2017 Hour : 12:14 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	