

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	192619 KM
File nr. :	1457731	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FQQ737 / WVWZZZ3CZEE048008 /		yr of constructionr :	/
E-File nr. :		First registration :	25/09/2013
VFS-nr. :		Color :	BLUE
Make + Model :	VOLKSWAGEN / PASSAT	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	SOA PEOPLE SA	Co2:	114g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :	PASSAT BER Comfortline BMT 105PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BERLINE	Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	4
HP:	105	kW:	77
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK
Cert. of reg. / Part 1:	OK	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :	
Warning vest :		Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	OK
Mobile phone kit :		Extinguisher :	[x]
First aid kit :	[x]	Warning triangle :	OK
Jack, wheelspanner :	OK [x]	Oil level :	OK
		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	BRIDGESTONE	Tyre :	OK	2-4/	Rim :	WHEEL SCRATCHED	/	Hubcap :
Wheel RL :	BRIDGESTONE	Tyre :	OK	>6/	Rim :	WHEEL SCRATCHED	/	Hubcap :
Wheel FR :	BRIDGESTONE	Tyre :	OK	2-4/	Rim :	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	BRIDGESTONE	Tyre :	OK	>6/	Rim :	WHEEL SCRATCHED	/	Hubcap :
Wheel RES:	ANDERE	Tyre :	OK	/	Rim :		/	Hubcap :

	Width	Height	Type	Rim	Index
Front tyre	215	55	R	16	V
Rear tyre	215	55	R	16	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR MUDGUARD/LEFT/Front	SCRATCH WITH PAINT DAMAGE	
[x]	REAR DOOR/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE	
[x]	REAR DOOR/RIGHT/Front	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE	
[x]	WINDSCREEN/RIGHT	CHIPS	
[x]	FRONT DOOR/RIGHT/REAR	DENT	2X DEUK ONDERAAN
[x]	BONNET/CENTER/LEFT/Front	DENT	
[x]	BONNET/CENTER/RIGHT/Front	CHIPS	

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/RIGHT/RIGHT	SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr.
2	10 LU =48.00 EUR	211.80 EUR		50 %
				Total
				259.80 EUR
[x]	REAR BUMPER/SIDE/LEFT/Front	SCRATCH WITH PAINT DAMAGE		MEERDERE LAKSCHADES
	Number	Code	Description	Unit price
	Depr.	Total		
0	0			
[x]	REAR MUDGUARD/RIGHT/Front	SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr.
3	0 LU =0.00 EUR	308.20 EUR		50 %
				Total
				308.20 EUR
[x]	REAR DOOR/LEFT/Front	DENT		2X
	Number	Code	Description	Unit price
	Depr.	Total		
1	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR
				Total
				63.00 EUR
	Number	Code	Description	Unit price
	Depr.	Total		
1	I 1	i-vab-uitd-02	BEAT OUT DENT SUPPL	19.80 EUR
				Total
				19.80 EUR

[x] REAR DOOR/RIGHT/REAR

SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
3 0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR

[x] FRONT DOOR/RIGHT/CENTER

DENT

Number	Code	Description	Unit price	Depr.	Total
4	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
4	I 1 i-vab-uitd-02	BEAT OUT DENT SUPPL	19.80 EUR		19.80 EUR

1	2	3	4	5	6	7	8	9	10
82.80	259.80	626.55	82.80	0	0	0	0	0	0
82.80	129.90	313.28	82.80	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
165.60	886.35	0	1051.95
HOG: 0	BG: 0		NA Deprec. 608.78
			0.00%
			TOTAL 608.78

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark : [x]		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 13/11/2017 Hour : 11:48 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	