

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: CLEAN [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	115455 KM
<b>File nr. :</b>	1458827	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1FMG763 / WVWZZZ3CZEE021553 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	16/08/2013
<b>VFS-nr. :</b>		<b>Color :</b>	BLUE D
<b>Make + Model :</b>	VOLKSWAGEN / PASSAT BREAK	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>	176	<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	EURO 5
<b>Customer company :</b>	SOLVAY SA	<b>Co2:</b>	113g/km
<b>Driver :</b>		<b>Remote controls:</b>	2
<b>Covering :</b>	TISSUE	<b>Number keys :</b>	2 [x]
<b>Vehicle kind :</b>	VEHICLE	<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>	PASSAT VAR Trendline BM 105PK	<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>	No	<b>Metallic paint:</b>	Yes
<b>Variant car:</b>	BREAK	<b>Engine size:</b>	1598
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	5
<b>Number of gears:</b>	6	<b>Number of doors:</b>	5
<b>HP:</b>	105	<b>kW:</b>	77
<b>Fisc HP</b>		<b>Imported vehicle:</b>	
<b>Animals transported:</b>	No	<b>Smoked in vehicle:</b>	No
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	No
		<b>Use:</b>	Unknown

**General condition:**

Original registr. number : OK	Service manual : OK
Cert. of reg. / Part 1:	Cert. of conformity : OK
Cert. of reg. copy / Part 2: OK	Insurance certificate :
Warning vest : OK	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK
Mobile phone kit :	Extinguisher : OK
First aid kit : OK	Warning triangle : OK
Jack, wheelspanner :	Oil level : OK
	Filled up : 0

## Wheels and tyres: Summer tires

Wheel FL:	UNIROYAL	Tyre :	OK	>6/	Rim :	/	Hubcap :	SCRATCHED
Wheel RL :	UNIROYAL	Tyre :	OK	4-6/	Rim :	/	Hubcap :	BROKEN / CRACKED
Wheel FR :	UNIROYAL	Tyre :	OK	>6/	Rim :	/	Hubcap :	
Wheel RR :	UNIROYAL	Tyre :	OK	4-6/	Rim :	/	Hubcap :	
Wheel RES:	ANDERE	Tyre :	OK	/	Rim :	/	Hubcap :	

  

	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	H
Rear tyre	205	55	R	16	H

Remark :

## Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :	

  

	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## Conclusion

### Bodywork \& windows

[x] BONNET/CENTER/LEFT OTHER DAMAGES OVBH POL.

### STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x] REAR BUMPER/LEFT/LEFT SCRATCH WITH PAINT DAMAGE

[x] REAR MUDGUARD/LEFT/REAR DENT 2X + POL.

[x] REAR MUDGUARD/RIGHT/FRONT SCRATCH WITH PAINT DAMAGE

[x] FRONT DOOR/RIGHT/REAR SCRATCH WITH PAINT DAMAGE ONDERAAN

[x] BONNET/CENTER/RIGHT/FRONT CHIPS

### Accessories and others

OUTSIDE MIRROR RIGHTHAND SIDE SCRATCH WITH PAINT DAMAGE

### STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x] REAR DOOR/LEFT/CORNER/BELOW DENT

	Repair paint - LI	New paint - E	Depr.	Total
1 0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR

[x] ROOF STYLE/CENTER/LEFT DENT

	Repair paint - LI	New paint - E	Depr.	Total
3 0 LU =0.00 EUR	220.18 EUR		50 %	220.18 EUR

[x] REAR DOOR/RIGHT/CENTER DENT

Number	Code	Description	Unit price	Depr.	Total
4	I1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR

[x] FRONT BUMPER/LEFT/CORNER SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

## Others

HUB CAP REAR L

	Repair paint - LI	New paint - E	Depr.	Total
5 0 LU =0.00 EUR			50 %	

## Pieces

Number	Code	Description	Unit price	Depr.	Total
5	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR

1	2	3	4	5	6	7	8	9	10
318.35	211.80	220.18	63.00	30.00	0	0	0	0	0
159.18	105.90	110.09	63.00	15.00	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
63.00	780.33	0	<b>843.33</b>
HOG: 0	BG: 0		NA Deprec. 453.16
			0.00%
			<b>TOTAL 453.16</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No <b>Reason :</b>		
<b>Remark :</b> NAVI OK		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 14/11/2017 <b>Hour :</b> 12:22 <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
Signature authorized by customer 	