

www.vabfleetservices.be Date: 13/11/2017 1/4

**DCPYCI** 

### [X] EFFECTIVE [ ] NOT EXECUTED

[X] COLLECTION

[ ] DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness:	INT: CLEAN [x] EXT: CLEAN [x]
Owner:		Mileage :	175369 KM
File nr. :	1458886	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1EKI250 / TMBGT61Z8	D2104414 /	yr of constructionr :	/
E-File nr. :		First registration :	04/01/2013
VFS-nr. :		Color :	BLACK
Make + Model :	SKODA / OCTAVIA BREAK	Fuel type :	DIESEL
Object nr. :	12055	Fuel :	
Classification:		Environment Class:	EURO 5
Customer company :	ERICSSON N.V./S.A.	Co2:	109g/km
Driver :		Remote controls:	2
Covering:	PARTIAL LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	OCTAVIA COMBI GTec Elegance DPF 105PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	5
HP:	105	kW:	77
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			



www.vabfleetservices.be Date: 13/11/2017 2/4

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:			Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD	OK	[x]
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]	Filled up :	0	

### Wheels and tyres: Winter tires

Wheel FL:	[x]	MICHELIN	Tyre:		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED	)	/ Hubcap:		
Wheel RL:	[x]	MICHELIN	Tyre:		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED	)	/ Hubcap:		
Wheel FR:	[x]	MICHELIN	Tyre:	[x]	OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED	)	/ Hubcap:		
Wheel RR:	[x]	MICHELIN	Tyre:		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED	)	/ Hubcap:		
Wheel RES:	[x]		Tyre:		OK		/	Rim:				/ Hubcap:		
														1

 [x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	M+S
Rear tyre	205	55	R	16	M+S

Remark:

### Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

[x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 13/11/2017 3/4

#### STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x] REAR BUMPER/CENTER/LEFT SCRATCH WITH PAINT DAMAGE

[x] FRONT DOOR/LEFT/REAR DENT

[x] FRONT BUMPER/CENTER/LEFT SCRATCH WITH PAINT DAMAGE

#### STATUS: NOT ACCEPTABLE

#### Others

RIM FRONT LEFT

	Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM REAR LEFT

	Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM FRONT RIGHT

	Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

1	2	3	4	5	6	7	8	9	10
285.00	0	0	0	0	0	0	0	0	0
285.00	0	0	0	0	0	0	0	0	0

	GENERAL	TRADITIONAL	INNOVATIVE
285.00	0	0	285.00
NA Deprec. 285.00		BG: 0	HOG: 0
0.00%			

0.00%
TOTAL 285.00



www.vabfleetservices.be Date: 13/11/2017 4/4

[x] = Status Modification

**Pictures:** No

**CIRCUMSTANCES** 

UNDER CONDITION - VEHICLE WET

Extra Time :	0 min		Waiting time: 0 min		Towing time :	0 min	
		Reason:			Reason:		
NOT EXECUTED:	No	•					
Reason:							
Remark :							
Prices in EUR w	ithout VAT						
Authorized by				Executed by VAB Fleet Se	rvices		
customer :							
Remark authorized customer :							
Date :	13/11/2017	Hour: 1	6:35				
Company :							
Executed by VAB Fl Services	eet						
E-Mail :	@						
Signature authorized b	by customer						