

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: DIRTY [x]
Owner :		Mileage :	147410 KM
File nr. :	1456466	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FPI198 / VF15RRL0H49477898 /		yr of constructionr :	/
E-File nr. :		First registration :	13/09/2013
VFS-nr. :		Color :	RED
Make + Model :	RENAULT / CLIO	Fuel type :	DIESEL
Object nr. :	34886	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	Cegelec SA	Co2:	90g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :	CLIO IV BER Dynamique St&St 90PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1461
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	5
HP:	90	kW:	66
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :		Transport licence :		
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :	OK	[x]	Oil level :	OK
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RES:	[x]	MICHELIN	Tyre :	OK	[x]	>6/	Rim :			/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	195	55	R	15	H
Rear tyre	195	55	R	15	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] REAR MUDGUARD/LEFT/CENTER SCRATCH (WITHOUT PAINT DAMAGE)
- [x] REAR WINDOW STYLE/CENTER/LEFT/UP SCRATCH (WITHOUT PAINT DAMAGE)
- [x] REAR MUDGUARD/RIGHT/FRONT OTHER DAMAGES

Interior

- [x] DOOR IN REAR RIGHT SCRATCHED
- [x] BOOT LID IN SCRATCHED

STATUS: NOT ACCEPTABLE

Bodywork \& windows

- [x] WINDSCREEN/CENTER/RIGHT WINDOW DAMAGE

Number	Code	Description	Unit price	Depr.	Total
5	I 1 i-vab-herstr-01	WINDOW REPAIR	58.80 EUR		58.80 EUR
[x]	FRONT MUDGUARD/RIGHT/FRONT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	176.14 EUR		50 %	176.14 EUR

Interior

[x]	CARPET FL	CUT / TORN			
		Repair paint - LI	New paint - E	Depr.	Total
1	40 LU =192.00 EUR	0 EUR		50 %	192.00 EUR

Accessories and others

[x]	OUTSIDE MIRROR RIGHTHAND SIDE	WINDOW DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
4	3 LU =14.40 EUR	0 EUR		50 %	14.40 EUR

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 2 specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR		29.16 EUR

RIM REAR RIGHT

Number	Code	Description	Unit price	Depr.	Total
3	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
3	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	CARPET	48.00 EUR	50 %	48.00 EUR

Number	Code	Description	Unit price	Depr.	Total
4	1	INDICATOR	12.00 EUR	50 %	12.00 EUR

1	2	3	4	5	6	7	8	9	10
269.16	176.14	190.00	26.40	58.80	0	0	0	0	0
149.16	88.07	190.00	13.20	58.80	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
277.96	442.54	0	720.50
HOG: 0	BG: 1		NA Deprec. 499.23
			0.00%
			TOTAL 499.23

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 14/11/2017 Hour : 13:24 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	