

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: DIRTY [x]
Owner :		Mileage :	179797 KM
File nr. :	1457103	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DXF282 / WVVZZZ3CZBE348654 /		yr of constructionr :	/
E-File nr. :		First registration :	01/01/1918
VFS-nr. :		Color :	BROWN
Make + Model :	VOLKSWAGEN / PASSAT BREAK	Fuel type :	DIESEL
Object nr. :	ONBEKEND	Fuel :	
Classification :		Environment Class:	
Customer company :	ONBEKEND	Co2:	g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	1 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	BREAK	Engine size:	
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:		kW:	
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number : NOK	Service manual :
Cert. of reg. / Part 1: NOK [x]	Cert. of conformity : NOK
Cert. of reg. copy / Part 2:	Insurance certificate :
Warning vest : OK [x]	Transport licence :
Tax certificate :	Navigation CD/SD/DVD OK [x]
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher : OK [x]
First aid kit : OK [x]	Warning triangle : OK [x]
Jack, wheelspanner :	Oil level : OK [x]
	Filled up : 0

Wheels and tyres: Summer tires

Wheel FL: [x] UNIROYAL	Tyre : OK [x] 4-6/	Rim : /	Hubcap :
Wheel RL : [x] UNIROYAL	Tyre : OK [x] >6/	Rim : /	Hubcap :
Wheel FR : [x] UNIROYAL	Tyre : [x] OK [x] 4-6/	Rim : /	Hubcap :
Wheel RR : [x] UNIROYAL	Tyre : OK [x] >6/	Rim : /	Hubcap :
Wheel RES: [x]	Tyre : OK /	Rim : /	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	215	55	R	16	H
Rear tyre	215	55	R	16	H

Remark :

Wheels and tyres:

Wheel FL:	Tyre : OK /	Rim : /	Hubcap :
Wheel RL :	Tyre : OK /	Rim : /	Hubcap :
Wheel FR :	Tyre : OK /	Rim : /	Hubcap :
Wheel RR :	Tyre : OK /	Rim : /	Hubcap :
Wheel RES:	Tyre : OK /	Rim : /	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	ROOF STYLE/FRONT/RIGHT/CENTER	OTHER DAMAGES	SLECHTE HERSTELLING		
Number	Code	Description	Unit price	Depr.	Total
0	0				

[x]	WINDSCREEN/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR	0.00 EUR		50 %	

[x]	WINDSCREEN/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE			
Number	Code	Description	Unit price	Depr.	Total
0	0				

[x]	BONNET/RIGHT/CENTER	OTHER DAMAGES	CHEM. INWERKING		
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	290.08 EUR		50 %	290.08 EUR

[x]	BONNET/CENTER/LEFT/FRONT	DENT			
Number	Code	Description	Unit price	Depr.	Total
0	0				

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 4	specifiek-per-kwartier-a-vab-rein-03 CLEANING INTERIOR	14.58 EUR		58.32 EUR

1	2	3	4	5	6	7	8	9	10
58.32	290.08	0.00	0	0	0	0	0	0	0
58.32	145.04	0.00	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL		
58.32	290.08	0		348.40
HOG: 0	BG: 0		NA Deprec.	203.36
			0.00%	
			TOTAL	203.36

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 13/11/2017 Hour : Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	