

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	150354 KM
File nr. :	1455448	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1HTE590 / WVWZZZ3CZFE028456 /		yr of constructionr :	/
E-File nr. :		First registration :	01/01/1918
VFS-nr. :		Color :	GREY
Make + Model :	VOLKSWAGEN / PASSAT BREAK	Fuel type :	DIESEL
Object nr. :	37158	Fuel :	
Classification :		Environment Class:	
Customer company :	VALUE RETAIL MANAGEMENT BELGIUM BVBA	Co2:	g/km
Driver :		Remote controls:	1
Covering :	LEATHER	Number keys :	1 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	BREAK	Engine size:	
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:		kW:	
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number : OK	Service manual :
Cert. of reg. / Part 1: NOK [x]	Cert. of conformity : NOK
Cert. of reg. copy / Part 2:	Insurance certificate :
Warning vest : OK [x]	Transport licence :
Tax certificate :	Navigation CD/SD/DVD OK [x]
Fuel card : [x]	Car radio : OK [x]
Mobile phone kit :	Extinguisher : OK [x]
First aid kit : OK [x]	Warning triangle : OK [x]
Jack, wheelspanner :	Oil level : OK [x]
	Filled up : 0

Wheels and tyres: Summer tires

Wheel FL: [x] KLÉBER Tyre : OK [x] 4-6/ Rim : / Hubcap :
Wheel RL : [x] CONTINENTAL Tyre : OK [x] 4-6/ Rim : [x] WHEEL SCRATCHED / Hubcap :
Wheel FR : [x] KLÉBER Tyre : [x] OK [x] 4-6/ Rim : [x] WHEEL SCRATCHED / Hubcap :
Wheel RR : [x] CONTINENTAL Tyre : OK [x] 4-6/ Rim : [x] WHEEL SCRATCHED / Hubcap :
Wheel RES: [x] Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	235	45	R	17	Y
Rear tyre	235	45	R	17	Y

Remark :

Wheels and tyres:

Wheel FL: Tyre : OK / Rim : / Hubcap :
Wheel RL : Tyre : OK / Rim : / Hubcap :
Wheel FR : Tyre : OK / Rim : / Hubcap :
Wheel RR : Tyre : OK / Rim : / Hubcap :
Wheel RES: Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/RIGHT		SCRATCH WITH PAINT DAMAGE				
		Repair paint - LI	New paint - E	Depr.	Total		
3	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR		
[x]	REAR MUDGUARD/RIGHT/FRONT		SCRATCH WITH PAINT DAMAGE	+DEUK			
		Repair paint - LI	New paint - E	Depr.	Total		
4	0 LU =0.00 EUR	308.20 EUR		50 %	308.20 EUR		
[x]	WINDOW STYLE REAR DOOR/RIGHT		DENT				
		Repair paint - LI	New paint - E	Depr.	Total		
6	0 LU =0.00 EUR	0 EUR		50 %			
		Repair paint - LI	New paint - E	Depr.	Total		
6	10 LU =48.00 EUR	0 EUR		50 %	48.00 EUR		
[x]	REAR DOOR/RIGHT/REAR		SCRATCH WITH PAINT DAMAGE	+DEUK			
		Repair paint - LI	New paint - E	Depr.	Total		
4	0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR		
[x]	BONNET/CENTER/LEFT/FRONT		DENT				
		Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR	

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 2	specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR	29.16 EUR

RIM REAR LEFT

Number	Code	Description	Unit price	Depr.	Total
5	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

RIM REAR RIGHT

Number	Code	Description	Unit price	Depr.	Total
5	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
5	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
6	1	RUITSTIJL	150.00 EUR	50 %	150.00 EUR

1	2	3	4	5	6	7	8	9	10
29.16	63.00	211.80	626.55	285.00	198.00	0	0	0	0
29.16	63.00	105.90	313.28	285.00	99.00	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
377.16	1036.35	0	1413.51
HOG: 0	BG: 0		NA Deprec. 895.34
			0.00%
			TOTAL 895.34

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 13/11/2017 Hour : Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	