

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: CLEAN [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	122857 KM
<b>File nr. :</b>	1458225	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1FNW880 / VF1JZ14M649418136 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	03/09/2013
<b>VFS-nr. :</b>		<b>Color :</b>	BROWN
<b>Make + Model :</b>	RENAULT / GRAND SCENIC	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>	49284	<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	EURO 5
<b>Customer company :</b>	RANDSTAD GROUP BELGIUM NV	<b>Co2:</b>	105g/km
<b>Driver :</b>		<b>Remote controls:</b>	2
<b>Covering :</b>	TISSUE	<b>Number keys :</b>	2 [x]
<b>Vehicle kind :</b>		<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>	GRAND SCENIC Expression 5pl.110PK	<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>	No	<b>Metallic paint:</b>	Yes
<b>Variant car:</b>	MONOVOLUME	<b>Engine size:</b>	1461
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	5
<b>Number of gears:</b>	6	<b>Number of doors:</b>	5
<b>HP:</b>	110	<b>kW:</b>	81
<b>Fisc HP</b>		<b>Imported vehicle:</b>	No
<b>Animals transported:</b>	No	<b>Smoked in vehicle:</b>	Yes
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	No
		<b>Use:</b>	Unknown

**General condition:**

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :		Transport licence :		
Tax certificate :		Navigation CD/SD/DVD	OK	[x]
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :	OK	[x]	Oil level :	OK
			Filled up :	0

## Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	4-6/	Rim :	/
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel RES:	[x]		Tyre :	OK	/		Rim :	/	Hubcap :
	[x]								[x] SCRATCHED

[x]	Width	Height	Type	Rim	Index
Front tyre	205	60	R	16	H
Rear tyre	205	60	R	16	H

Remark :

## Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x]	REAR DOOR/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE	
[x]	ROOF STYLE/CENTER/LEFT	DENT	
[x]	REAR DOOR/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE	POL
[x]	REAR DOOR/RIGHT/CENTER	DENT	
[x]	FRONT DOOR/LEFT/REAR	DENT	
[x]	FRONT DOOR/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE	POL
[x]	BONNET/CENTER/LEFT	DENT	

### Interior

[x]	DOOR IN REAR L	SCRATCHED
-----	----------------	-----------

### Accessories and others

[x]	OUTSIDE MIRROR RIGHTHAND SIDE	SCRATCH (WITHOUT PAINT DAMAGE)
-----	-------------------------------	--------------------------------

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	REAR DOOR/CENTER/RIGHT	DENT			
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
4	0 LU =0.00 EUR	301.68 EUR		50 %	301.68 EUR
[x]	REAR MUDGUARD/RIGHT/REAR	DENT			
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
5	0 LU =0.00 EUR	308.20 EUR		50 %	308.20 EUR
[x]	REAR BUMPER/SIDE/RIGHT/FRONT	SCRATCH WITH PAINT DAMAGE			
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
5	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR
[x]	REAR THRESHOLD/RIGHT/FRONT	DENT			
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
6	0 LU =0.00 EUR	310.50 EUR		50 %	310.50 EUR

[x]	FRONT BUMPER/RIGHT/SIDE	SCRATCH WITH PAINT DAMAGE			
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
2	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

[x]	ROOF/CENTER/LEFT	DENT			
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
3	1 1 i-vab-uitd-01	BEAT OUT DENT		63.00 EUR	63.00 EUR

### Interior

[x]	SEAT FL	BURNT			
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
1	25 LU =120.00 EUR	0 EUR		50 %	120.00 EUR

### Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	SEAT UPHOLSTERY TISSUE	120.00 EUR	50 %	120.00 EUR
2	1	CHROOM	40.00 EUR	50 %	40.00 EUR
2	1	SPOILER	60.00 EUR	50 %	60.00 EUR

1	2	3	4	5	6	7	8	9	10
240.00	311.80	63.00	301.68	520.00	310.50	0	0	0	0
120.00	155.90	63.00	150.84	260.00	155.25	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
63.00	1683.98	0	<b>1746.98</b>
HOG: 0	BG: 0		NA Deprec. <b>904.99</b>
			0.00%
			<b>TOTAL 904.99</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No <b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 14/11/2017 <b>Hour :</b> 12:59 <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
Signature authorized by customer 	